


Lot Space # _____ Summs Reference No 341974

Client <u>City of Chesapeake</u> Lien Holder		Vehicle Info	
Customer Name _____		Year <u>2011</u> Make <u>Ford</u> Color <u>white</u>	
Asset # <u>E1274</u>		Model <u>Crown Vic</u> Doors _____ Ebrake: Yes / No	
Unit Secured From <u>956 Greenbrier Pkwy</u>		License No. _____ State _____ Exp. Date _____	
Date Recovered <u>10/22/25</u> P/U By <u>800</u> Tow By & Truck # <u>130</u> Tow from For R		Mileage <u>178494</u> ☐ Won't Display Lasso lock: Yes / No	
Time: <u>3:00</u> AM or PM <u>PM</u>		Heavy Damage: Yes / No	Airbags Deployed: Yes / No
Storage Address: Summs Skip and Collateral Solutions 2616 Quality Court Virginia Beach, VA 23454		K ☐ Ignition <u>3</u> E ☐ Transponder Y ☐ Push Button S ☐ No Key ☐ FOB ☐ Keys ☐ Has Keys Does not Run or Start	
Release Hours By Appointment Only		Customer Aware? <u>Yes/No</u> Able to Get Into Unit? <u>Yes/No</u> Insp Vehicle Locked at Time of Repo? <u>Yes/No</u> Fuel: E, 1/4, 1/2, 3/4, F Personals? <u>Yes/No</u> Glove/Center Box Access <u>Yes/No</u> Trunk Access? <u>Yes/No</u> Keys? <u>Yes/No</u> How Many _____ How Many FOBS _____	
VIN <u>2FABP7BV9BX139025</u>			



Completed While

General Condition of Collateral

M E C H A N I C A L	Engine	☒ OK	☐ Rough	☐ Burns Oil
	Transmission	☒ OK	☐ Slips	☐ Leaks Oil
	Clutch	☐ OK	☐ Fair	☐ Slips
	Brakes	☐ OK	☒ Fair	☐ Pull Grab
T I R E S	Battery	☒ Yes ☐ No	☐ OK	☐ Dead ☐ Disc..
	Engine Intact	☒ Yes ☐ No	This condition report was completed by a non mechanic and unit not road tested.	
	L. Front	☒ Good	☐ Fair	☐ Poor
	L. Rear	☒ Good	☐ Fair	☐ Poor
G L A S S	R. Front	☒ Good	☐ Fair	☐ Poor
	R. Rear	☒ Good	☐ Fair	☐ Poor
	Spare	☐ Jack	☐ Spare Wheel	☐ Duals
	Windshield	☒ OK	☐ Crk	☐ Chip
I N T E R I O R	L. Front	☒ Good	☐ Fair	☐ Poor
	L. Rear	☒ Good	☐ Fair	☐ Poor
	R. Front	☒ Good	☐ Fair	☐ Poor
	R. Rear	☒ Good	☐ Fair	☐ Poor
E Q U I P M E N T	Rearview	☒ Good	☐ Fair	☐ Poor
	Inst Panel	☒ Good	☐ Fair	☐ Poor
	F. Seats	☒ Good	☐ Fair	☐ Poor
	R. Seats	☒ Good	☐ Fair	☐ Poor
D O O R P A N E L S	Door Panels	☒ Good	☐ Fair	☐ Poor
	Mat Carpet	☒ Good	☐ Fair	☐ Poor
	Headliner	☒ Good	☐ Fair	☐ Poor
	Trunk	☒ Good	☐ Fair	☐ Poor

Completed By _____

Date _____

Comments hood latch broken
engine light on
tire light on

Auction/Dealer Receipt for Repossession

Date _____ Time _____

The undersigned acknowledges receipt of the above described vehicle in identical condition listed above.

Printed Name _____

Signature _____

Witness _____