


Lot Space # _____

Summs Reference No 341977

Client <u>City of Chesapeake</u> Lien Holder		Vehicle Info	
Customer Name _____		Year <u>2013</u> Make <u>Ford</u> Color <u>black/white</u>	
Asset # <u>E1332</u>		Model <u>Taurus</u> Doors _____ Ebrake: Yes / No	
Unit Secured From <u>956 Greenbrier Pkwy</u>		License No. _____ State _____ Exp. Date _____	
Date Recovered <u>10/22/25</u>		Mileage <u>149,021</u> ☐ Won't Display Lasso lock: Yes / No	
Time: <u>1030</u> AM or PM		Heavy Damage: Yes / No Airbags Deployed: Yes / No	
Storage Address: Summs Skip and Collateral Solutions 2616 Quality Court Virginia Beach, VA 23454		P/U By <u>807</u> Tow By & Truck # <u>132</u> Tow from F or R Used ☐ Go Jacks ☐ Dolly ☐ Roll Back ☐ None ☐ Shift Lock Customer Aware? <u>Yes/No</u> Able to Get Into Unit? <u>Yes/No</u> Insp Vehicle Locked at Time of Repo? <u>Yes/No</u> Fuel: E, 1/4, 1/2, 3/4, F Personals? <u>Yes/No</u> Glove/Center Box Access <u>Yes/No</u> Trunk Access? <u>Yes/No</u> Keys? <u>Yes/No</u> How Many _____ How Many FOBS _____	
Release Hours By Appointment Only		K ☒ Ignition E ☐ Transponder Y ☐ Push Button S ☐ No Key ☐ FOB ☐ Keys ☐ Has Keys Does not Run or Start	
VIN <u>1 F A H P 2 L 8 4 D G 1 7 5 9 3 3</u>			



Completed While
☐ Sunny ☐ Frost on Car ☐ Rainy/Wet
☐ Snow ☐ Ice Over ☐ Night

General Condition of Collateral
☐ Good ☐ Average ☐ Poor

M E C H A N I C A L	Engine	☒ OK	☐ Rough	☐ Burns Oil	
	Transmission	☒ OK	☐ Slips	☐ Leaks Oil	
	Clutch	☐ OK	☐ Fair	☐ Slips	
	Brakes	☒ OK	☐ Fair	☐ Pull Grab	
	Battery	☒ Yes ☐ No	☐ OK	☐ Dead ☐ Disc..	
Engine Intact: ☒ Yes ☐ No This condition report was completed by a non mechanic and unit not road tested.					
T I R E S	L. Front	☒ Good	☐ Fair	☐ Poor	☐ None
	L. Rear	☐ Good	☒ Fair	☐ Poor	☐ None
	R. Front	☐ Good	☒ Fair	☐ Poor	☐ None
	R. Rear	☐ Good	☒ Fair	☐ Poor	☐ None
	Spare	☐ Good	☒ Fair	☐ Poor	☐ None
☐ Jack ☐ Spare Wheel ☐ Duals					
G L A S S	Windshield	☒ OK	☐ Crk	☐ Chip	☐ Missing
	L. Front	☒ OK	☐ Crk	☐ Chip	☐ Missing
	L. Rear	☒ OK	☐ Crk	☐ Chip	☐ Missing
	R. Front	☒ OK	☐ Crk	☐ Chip	☐ Missing
	R. Rear	☒ OK	☐ Crk	☐ Chip	☐ Missing
I N T E R I O R	Inst Panel	☒ Good	☐ Fair	☐ Poor	☐ None
	F. Seats	☐ Good	☒ Fair	☐ Poor	☐ None
	R. Seats	☐ Good	☒ Fair	☐ Poor	☐ None
	Door Panels	☐ Good	☒ Fair	☐ Poor	☐ None
	Mat Carpet	☐ Good	☒ Fair	☐ Poor	☐ None
EQUIPMENT	☒ A/C ☐ Rear A/C ☒ Auto Trans ☐ 3rd Row ☐ Manual Trans ☐ Navigation ☒ Power Steering ☐ Backup Camera ☒ Power Brakes ☐ Heated Seats ☒ Power Windows ☐ Cooled Seats ☐ Power Seats ☐ Power Door Locks ☐ Power Mirrors ☐ Cruise Control ☐ Tilt Wheel ☐ Sun Roof ☐ AM FM ☒ CD ☐ DVD ☐ Amp Subwoofer ☐ Touch Display ☐ Leather Seats ☐ EV Charger ☐ Breathalyzer ☐ Trailer Hitch ☐ Bed Liner ☐ Step Rails ☐ Tool Box Locked Yes / No ☐ Bad Cover or Cap Locked Yes / No ☒ Hubcaps # <u>4</u> ☒ Factory Rims ☐ Aftermarket Rims				

Completed By _____ Date _____

Comments _____

Auction/Dealer Receipt for Repossession

Date _____ Time _____

The undersigned acknowledges receipt of the above described vehicle in identical condition listed above.

Printed Name _____

Signature _____

Witness _____