


Client <u>City of Chesapeake</u>	Vehicle Info	Year <u>2015</u> Make <u>Ford</u> Color <u>White/black</u>
Customer Name _____	Model <u>Taurus</u> Doors _____	Ebrake: Yes / No _____
Asset # <u>E1381</u>	License No. _____ State _____	Exp. Date _____
Unit Secured From <u>956 Greenbrier Pkwy</u>	Mileage <u>213485</u> Wont Display _____	Lasso lock: Yes / No _____
Date Recovered <u>10/23/25</u>	Heavy Damage: Yes / No _____	Airbags Deployed: Yes / No _____
Time: <u>11:00</u> AM or PM _____	P/U By <u>807</u> Tow By & Truck # <u>132</u> Tow from F or R _____	☐ Ignition
Storage Address: _____	Used ☐ Go Jacks ☐ Dolly ☐ Roll Back ☐ None ☐ Shift Lock	☐ Transponder
☒ Sumins Skip and Collateral Solutions 2616 Quality Court Virginia Beach, VA 23454	Customer Aware? <u>Yes/No</u> Able to Get Into Unit? <u>Yes/No</u> Insp _____	☐ Push Button
Release Hours By Appointment Only	Vehicle Locked at Time of Repo? <u>Yes/No</u> Fuel: E, 1/4, 1/2, 3/4, F _____	☐ No Key
	Personals? <u>Yes/No</u> Glove/Center Box Access <u>Yes/No</u> Trunk Access? <u>Yes/No</u>	☐ FOB
	Keys? <u>Yes/No</u> How Many _____ How Many FOBS _____	☐ Keys
		☐ Has Keys Does not Run or Start

VIN 1FAHP2L87FG100758



Completed While

☐ Sunny ☐ Frost on Car ☐ Rainy/Wet ☐ Night
☐ Snow ☐ Ice Over ☐

General Condition of Collateral

☐ Good ☐ Average ☐ Poor

M E C H A N I C A L	Engine	☒ OK	☐ Rough	☐ Burns Oil	
	Transmission	☒ OK	☐ Slips	☐ Leaks Oil	
	Clutch	☐ OK	☐ Fair	☐ Slips	
	Brakes	☐ OK	☒ Fair	☐ Pull Grab	
	Battery	☐ Yes ☐ No	☒ OK	☐ Dead ☐ Disc..	
Engine Intact: ☒ Yes ☐ No This condition report was completed by a non mechanic and unit not road tested.					
T I R E S	L. Front	☒ Good	☐ Fair	☐ Poor	☐ None
	L. Rear	☐ Good	☒ Fair	☐ Poor	☐ None
	R. Front	☐ Good	☒ Fair	☐ Poor	☐ None
	R. Rear	☐ Good	☒ Fair	☐ Poor	☐ None
	Spare	☐ Good	☐ Fair	☐ Poor	☐ None
☐ Jack ☐ Spare Wheel ☐ Duals					
G L A S S	Windshield	☒ OK	☐ Crk	☐ Chip	☐ Missing
	L. Front	☐ OK	☒ Crk	☐ Chip	☐ Missing
	L. Rear	☐ OK	☒ Crk	☐ Chip	☐ Missing
	R. Front	☐ OK	☒ Crk	☐ Chip	☐ Missing
	R. Rear	☐ OK	☒ Crk	☐ Chip	☐ Missing
I N T E R I O R	Inst Panel	☒ Good	☐ Fair	☐ Poor	☐ None
	F. Seats	☐ Good	☐ Fair	☐ Poor	☐ None
	R. Seats	☐ Good	☐ Fair	☐ Poor	☐ None
	Door Panels	☐ Good	☐ Fair	☐ Poor	☐ None
	Mat Carpet	☐ Good	☐ Fair	☐ Poor	☐ None
Headliner	☐ Good	☐ Fair	☐ Poor	☐ None	

EQUIPMENT

- ☒ A/C
- ☐ Rear A/C
- ☐ Auto Trans
- ☐ 3rd Row
- ☐ Manual Trans
- ☐ Navigation
- ☐ Power Steering
- ☐ Backup Camera
- ☐ Power Brakes
- ☐ Heated Seats
- ☐ Power Windows
- ☐ Coated Seats
- ☐ Power Seats
- ☐ Power Door Locks
- ☐ Power Mirrors
- ☐ Cruise Control
- ☐ Tilt Wheel
- ☐ Sun Roof
- ☐ AM FM ☐ DVD
- ☐ Amp. Subwoofer
- ☐ Touch Display
- ☐ Leather Seats
- ☐ EV Charger
- ☐ Breathalyzer
- ☐ Trailer Hitch
- ☐ Bed Liner
- ☐ Step Rails
- ☐ Tool Box Locked Yes / No _____
- ☐ Bed Cover or Cap Locked Yes / No _____
- ☐ Hubcaps # _____
- ☐ Factory Rims
- ☐ Aftermarket Rims

Completed By _____

Date _____

Comments _____

Auction/Dealer Receipt for Repossession

Date _____ Time _____

The undersigned acknowledges receipt of the above described vehicle in identical condition listed above.

Printed Name _____

Signature _____

Witness _____