


Lot Space # _____ Summis Reference No 341999

Client <u>City of Chesapeake</u>	Lien Holder	Vehicle Info	Year <u>2015</u> Make <u>Ford</u> Color <u>Blk/white</u>
Customer Name		Model <u>Taurus</u> Doors	Ebrake: Yes / No
Asset # <u>E1403</u>		License No. State	Exp. Date
Unit Secured From <u>956 Greenview Pkwy</u>		Mileage <u>168030</u> ☐ Won't Display	Lasso lock: Yes / No
		Heavy Damage: Yes / No	Airbags Deployed: Yes / No
Date Recovered <u>10/22/25</u>	P/U By <u>807</u> Tow By & Truck # <u>132</u> Tow from F or R	☐ Ignition ☐ Transponder ☐ Push Button ☐ No Key ☐ FOB ☒ Keys <u>1</u> ☐ Has Keys Does not Run or Start	
Time: <u>300</u> AM or <u>PM</u>	Used ☐ Go Jacks ☐ Dolly ☐ Roll Back ☐ None ☐ Shift Lock		
Storage Address: Summis Skip and Collateral Solutions 2616 Quality Court Virginia Beach, VA 23454	Customer Aware? <u>Yes/No</u> Able to Get Into Unit? <u>Yes/No</u> Insp. <u>926</u>		
Release Hours By Appointment Only	Vehicle Locked at Time of Repo? <u>Yes/No</u> Fuel: E, 1/4, 1/2, <u>3/4</u> , F		
	Personals? <u>Yes/No</u> Glove/Center Box Access <u>Yes/No</u> Trunk Access? <u>Yes/No</u>		
	Keys? <u>Yes/No</u> How Many _____ How Many FOBS _____		
VIN <u>1FAHP2L88FG122736</u>			



Completed While

General Condition of Collateral

☐ Sunny ☐ Frost on Car ☐ Rainy/Wet
☐ Snow ☐ Ice Over ☐ Night

☐ Good ☒ Average ☐ Poor

M E C H A N I C A L	Engine	☒ OK	☐ Rough	☐ Burns Oil	
	Transmission	☐ OK	☐ Slips	☐ Leaks Oil	
	Clutch	☐ OK	☐ Fair	☐ Slips	
	Brakes	☒ OK	☐ Fair	☐ Pull Grab	
	Battery	☒ Yes ☐ No	☒ OK	☐ Dead ☐ Disc..	
Engine Intact: ☐ Yes ☐ No This condition report was completed by a non mechanic and unit not road tested.					
T I R E S	L. Front	☒ Good	☐ Fair	☐ Poor	☐ None
	L. Rear	☐ Good	☐ Fair	☐ Poor	☐ None
	R. Front	☐ Good	☐ Fair	☐ Poor	☐ None
	R. Rear	☐ Good	☐ Fair	☐ Poor	☐ None
	Spare	☐ Good	☐ Fair	☐ Poor	☐ None
G L A S S	Windshield	☒ Good	☐ Fair	☐ Poor	☐ None
	L. Front	☐ Good	☐ Fair	☐ Poor	☐ None
	L. Rear	☐ Good	☐ Fair	☐ Poor	☐ None
	R. Front	☐ Good	☐ Fair	☐ Poor	☐ None
	R. Rear	☐ Good	☐ Fair	☐ Poor	☐ None
I N T E R I O R	Inst Panel	☒ Good	☐ Fair	☐ Poor	☐ None
	F. Seats	☐ Good	☐ Fair	☐ Poor	☐ None
	R. Seats	☐ Good	☐ Fair	☐ Poor	☐ None
	Door Panels	☐ Good	☐ Fair	☐ Poor	☐ None
	Mat Carpet	☐ Good	☐ Fair	☐ Poor	☐ None
E Q U I P M E N T	☐ Jack	☐ Spare Wheel	☐ Duals		
	☒ A/C	☐ Rear A/C			
	☒ Auto Trans	☐ 3rd Row			
	☒ Manual Trans	☐ Navigation			
	☒ Power Steering	☐ Backup Camera			
	☒ Power Brakes	☐ Heated Seats			
	☒ Power Windows	☐ Cooled Seats			
	☒ Power Seats				
	☒ Power Door Locks				
	☒ Power Mirrors				
	☒ Cruise Control				
	☐ Tilt Wheel				
	☐ Sun Roof				
	☒ AM FM ☐ CD ☐ DVD				
	☐ Amp Subwoofer				
☐ Touch Display					
☐ Leather Seats					
☐ EV Charger					
☐ Breathalyzer					
☐ Trailer Hitch					
☐ Bed Liner					
☐ Step Rails					
☐ Tool Box Locked Yes / No					
☐ Bed Cover or Cap Locked Yes / No					
☒ Hubcaps # _____					
☐ Factory Rims					
☐ Aftermarket Rims					

Completed By

Date

Comments

Auction/Dealer Receipt for Repossession

Date _____ Time _____

The undersigned acknowledges receipt of the above described vehicle in identical condition listed above.

Printed Name _____

Signature _____

Witness _____