


Lot Space # _____ Summis Reference No 342000

Client <u>City of Chesapeake</u>	Lien Holder <u>Chesapeake</u>	Vehicle Info
Customer Name _____	Year <u>2015</u> Make <u>Ford</u> Color <u>black/white</u>	Model <u>TAURUS</u> Doors _____
Asset # <u>E1441</u>	License No. _____ State _____ Exp. Date _____	Ebrake: Yes / No
Unit Secured From <u>956 Greenbrier Pkwy</u>	Mileage <u>239,215</u> ☐ Won't Display	Lasso lock: Yes / No
Date Recovered <u>10/22/25</u>	Heavy Damage: Yes / No	Airbags Deployed: Yes / No
Time: <u>1030</u> AM or PM	P/U By <u>807</u> Tow By & Truck # <u>132</u> Tow from F or R	☒ Ignition <u>2</u>
Storage Address: ☒ Summis Skip and Collateral Solutions 2616 Quality Court Virginia Beach, VA 23454	Used ☐ Go Jacks ☐ Dolly ☐ Roll Back ☐ None ☐ Shift Lock	☐ Transponder
Release Hours By Appointment Only	Customer Aware? <u>Yes/No</u> Able to Get Into Unit? <u>Yes/No</u> Insp	☐ Push Button
	Vehicle Locked at Time of Repo? <u>Yes/No</u> Fuel: <u>E</u> 1/4, 1/2, 3/4, F	☐ No Key
	Personals? <u>Yes/No</u> Glove/Center Box Access <u>Yes/No</u> Trunk Access? <u>Yes/No</u>	☐ FOB
	Keys? <u>Yes/No</u> How Many _____ How Many FOBS _____	☐ Keys
		☐ Has Keys Does not Run or Start

VIN 1 F A H P 2 L 8 7 F G 2 0 8 0 8 9

Completed While
☐ Sunny ☐ Frost on Car ☐ Rainy/Wet
☐ Snow ☐ Ice Over ☐ Night

General Condition of Collateral
☐ Good ☒ Average ☐ Poor

Engine	☒ OK	☐ Rough	☐ Burns Oil
Transmission	☒ OK	☐ Slips	☐ Leaks Oil
Clutch	☐ OK	☐ Fair	☐ Slips
Brakes	☒ OK	☐ Fair	☐ Pull Grab
Battery	☒ Yes ☐ No	☐ OK	☐ Dead ☐ Disc..
Engine Intact: ☒ Yes ☐ No This condition report was completed by a non mechanic and unit not road tested.			

	Good	Fair	Poor	None
L. Front	☒			
L. Rear		☒		
R. Front		☒		
R. Rear		☒		
Spare	☒			
Jack	☐	☐ Spare Wheel	☐ Duals	
Windshield	☒	☐ OK	☐ Crk	☐ Chip ☐ Missing
L. Front	☒			
L. Rear	☒			
R. Front	☒			
R. Rear	☒			
Rearview	☒			
Inst Panel	☒			
F. Seats		☒		
R. Seats		☒		
Door Panels		☒		
Mat Carpet		☒		
Headliner		☒		

EQUIPMENT

☒ A/C	☐ Rear A/C
☒ Auto Trans	☐ 3rd Row
☐ Manual Trans	☐ Navigation
☒ Power Steering	☐ Backup Camera
☐ Power Brakes	☐ Heated Seats
☐ Power Windows	☐ Cooled Seats
☐ Power Seats	
☐ Power Door Locks	
☐ Power Mirrors	
☐ Cruise Control	
☐ Tire Wheel	
☐ Sun Roof	
☒ AM FM ☐ CD ☐ DVD	
☐ Amp Subwoofer	
☐ Touch Display	
☐ Leather Seats	
☐ EV Charger	
☐ Breathalyzer	
☐ Trailer Hitch	
☐ Bad Liner	
☐ Step Rails	
☐ Tool Box: Locked Yes / No	
☐ Bad Cover or Cap: Locked Yes / No	
☒ Hubcaps # <u>107</u>	
☒ Factory Rims	
☐ Aftermarket Rims	

Completed By _____

Date _____

Comments fire light on

Auction/Dealer Receipt for Repossession

Date _____ Time _____

The undersigned acknowledges receipt of the above described vehicle in identical condition listed above.

Printed Name _____

Signature _____

Witness _____