


Lot Space # _____

Summs Reference No 342001

Client <u>City of Chesapeake</u> Lien Holder		Vehicle Info	
Customer Name _____		Year <u>2016</u> Make <u>Ford</u> Color <u>black/white</u>	
Asset # <u>E1454</u>		Model <u>Taurus</u> Doors _____	Ebrake: Yes / No
Unit Secured From <u>956 Greenbrier Pkwy</u>		License No. _____ State _____ Exp. Date _____	
Date Recovered <u>10/22/25</u>		Mileage <u>196942</u> ☐ Won't Display	Lasso lock: Yes / No
Time: <u>3:00</u> AM or PM		Heavy Damage: Yes / No	Airbags Deployed: Yes / No
Storage Address: Summs Skip and Collateral Solutions 2616 Quality Court Virginia Beach, VA 23454		P/U By <u>807</u> Tow By & Truck # <u>132</u> Tow from F or R Used ☐ Go Jacks ☐ Dolly ☐ Roll Back ☐ None ☐ Shift Lock Customer Aware? <u>Yes/No</u> Able to Get Into Unit? <u>Yes/No</u> Insp Vehicle Locked at Time of Repo? <u>Yes/No</u> Fuel: E, 1/4, 1/2, 3/4, F Personals? <u>Yes/No</u> Glove/Center Box Access <u>Yes/No</u> Trunk Access? <u>Yes/No</u> Keys? <u>Yes/No</u> How Many _____ How Many FOBS _____	
Release Hours By Appointment Only		K ☐ Ignition <u>2</u> E ☐ Transponder Y ☐ Push Button S ☐ No Key ☐ FOB ☐ Keys ☐ Has Keys Does not Run or Start	
VIN <u>1FAHP2L87GG143739</u>			



M E C H A N I C A L	Engine	☒ OK	☐ Rough	☐ Burns Oil	
	Transmission	☒ OK	☐ Slips	☐ Leaks Oil	
	Clutch	☐ OK	☐ Fair	☐ Slips	
	Brakes	☐ OK	☒ Fair	☐ Pull Grab	
	Battery	☒ Yes ☐ No ☒ OK	☐ Dead	☐ Disc..	
	Engine Intact	☐ Yes ☒ No	This condition report was completed by a non mechanic and unit not road tested.		
T I R E S	L. Front	☒ Good	☐ Fair	☐ Poor	☐ None
	L. Rear	☐ Good	☒ Fair	☐ Poor	☐ None
	R. Front	☐ Good	☒ Fair	☐ Poor	☐ None
	R. Rear	☐ Good	☒ Fair	☐ Poor	☐ None
	Spare	☐ Jack	☐ Spare Wheel	☐ Duals	
G L A S S	Windshield	☒ OK	☐ Crk	☐ Chip	☐ Missing
	L. Front	☐ Good	☒ Fair	☐ Poor	☐ None
	L. Rear	☐ Good	☒ Fair	☐ Poor	☐ None
	R. Front	☐ Good	☒ Fair	☐ Poor	☐ None
	R. Rear	☐ Good	☒ Fair	☐ Poor	☐ None
	Rearview	☐ Good	☒ Fair	☐ Poor	☐ None
I N T E R I O R	Inst Panel	☒ Good	☐ Fair	☐ Poor	☐ None
	F. Seats	☐ Good	☒ Fair	☐ Poor	☐ None
	R. Seats	☐ Good	☒ Fair	☐ Poor	☐ None
	Door Panels	☐ Good	☒ Fair	☐ Poor	☐ None
	Mat Carpet	☐ Good	☒ Fair	☐ Poor	☐ None
	Headliner	☐ Good	☒ Fair	☐ Poor	☐ None

Completed While

General Condition of Collateral

EQUIPMENT

- ☐ A/C
- ☐ Auto Trans
- ☐ Manual Trans
- ☐ Power Steering
- ☐ Power Brakes
- ☐ Power Windows
- ☐ Power Seats
- ☐ Power Door Locks
- ☐ Power Mirrors
- ☐ Cruise Control
- ☐ Tilt Wheel
- ☐ Sun Roof
- ☐ AM FM ☐ CD ☐ DVD
- ☐ Amp Subwoofer
- ☐ Touch Display
- ☐ Leather Seats
- ☐ EV Charger
- ☐ Breathalyzer
- ☐ Trailer Hitch
- ☐ Bed Liner
- ☐ Step Rails
- ☐ Tool Box Locked Yes / No
- ☐ Bed Cover or Cap Locked Yes / No
- ☐ Hubcaps # _____
- ☐ Factory Rims
- ☐ Aftermarket Rims
- ☐ Rear A/C
- ☐ 3rd Row
- ☐ Navigation
- ☐ Backup Camera
- ☐ Heated Seats
- ☐ Cooled Seats

Completed By _____

Date _____

Comments _____

Auction/Dealer Receipt for Repossession

Date _____ Time _____

The undersigned acknowledges receipt of the above described vehicle in identical condition listed above.

Printed Name _____

Signature _____

Witness _____