

Lot Space # _____ Summa Reference No 342002

Client <u>City of Chesapeake</u>	Lien Holder	Vehicle Info	Year <u>2011</u> Make <u>Ford</u> Color <u>black/white</u>
Customer Name		Model <u>Taurus</u> Doors <u>4</u>	Ebrake: Yes / No
Asset # <u>E1456</u>		License No. _____ State _____ Exp. Date _____	
Unit Secured From <u>956 Greenbrier Pkwy</u>		Mileage <u>209,071</u> ☐ Won't Display	Lasso lock: Yes / No
		Heavy Damage: Yes / No <u>(No)</u>	Airbags Deployed: Yes / No <u>(No)</u>
Date Recovered <u>10/23/25</u>	P/U By <u>807</u> Tow By & Truck # <u>132</u> Tow from <u>For R</u>	☒ Ignition <u>1</u> ☐ Transponder ☐ Push Button ☐ No Key ☐ FOB ☐ Keys ☐ Has Keys Does not Run or Start	
Time: <u>11:00</u> AM or PM	Used ☐ Go Jacks ☐ Dolly ☐ Roll Back ☐ None ☐ Shift Lock	Customer Aware? <u>Yes/No</u> Able to Get Into Unit? <u>Yes/No</u> Insp <u>7/25</u>	
Storage Address: ☒ Summa Skip and Collateral Solutions 2616 Quality Court Virginia Beach, VA 23454	Vehicle Locked at Time of Repo? <u>Yes/No</u> Fuel: E, 1/4, 1/2, 3/4, F	Personals? <u>Yes/No</u> Glove/Center Box Access <u>Yes/No</u> Trunk Access? <u>Yes/No</u>	
Release Hours By Appointment Only	Keys? <u>Yes/No</u> How Many <u>1</u> How Many FOBS _____		

VIN 2 F A H P 2 L 8 1 G G 1 4 2 0 7 0

rust* *bumper loose* *paint peeling throughout

Completed While
☐ Sunny ☐ Frost on Car ☐ Rainy/Wet
☐ Snow ☐ Ice Over ☐ Night

General Condition of Collateral
☐ Good ☒ Average ☐ Poor

M E C H A N I C A L	Engine	☒ OK	☐ Rough	☐ Burns Oil	
	Transmission	☒ OK	☐ Slips	☐ Leaks Oil	
	Clutch	☐ OK	☐ Fair	☐ Slips	
	Brakes	☒ OK	☐ Fair	☐ Pull Grab	
	Battery	☒ Yes ☐ No	☐ OK	☐ Dead ☐ Disc..	
Engine Intact: ☒ Yes ☐ No This condition report was completed by a non mechanic and unit not road tested.					
T I R E S	L. Front	☒ Good	☐ Fair	☐ Poor	☐ None
	L. Rear	☒ Good	☐ Fair	☐ Poor	☐ None
	R. Front	☒ Good	☐ Fair	☐ Poor	☐ None
	R. Rear	☒ Good	☐ Fair	☐ Poor	☐ None
	Spare	☐ Jack	☐ Spare Wheel	☐ Duals	
G L A S S	Windshield	☒ OK	☐ Crk	☐ Chip	☐ Missing
	L. Front	☒ OK	☐ Crk	☐ Chip	☐ Missing
	L. Rear	☒ OK	☐ Crk	☐ Chip	☐ Missing
	R. Front	☒ OK	☐ Crk	☐ Chip	☐ Missing
	R. Rear	☒ OK	☐ Crk	☐ Chip	☐ Missing
I N T E R I O R	Inst Panel	☒ Good	☐ Fair	☐ Poor	☐ None
	F. Seats	☒ Good	☐ Fair	☐ Poor	☐ None
	R. Seats	☒ Good	☐ Fair	☐ Poor	☐ None
	Door Panels	☒ Good	☐ Fair	☐ Poor	☐ None
	Mat Carpet	☒ Good	☐ Fair	☐ Poor	☐ None

EQUIPMENT

☒ A/C	☐ Rear A/C
☐ Auto Trans	☐ 3rd Row
☐ Manual Trans	☐ Navigation
☒ Power Steering	☒ Backup Camera
☒ Power Brakes	☐ Heated Seats
☒ Power Windows	☐ Cooled Seats
☒ Power Seats	
☐ Power Door Locks	
☒ Power Mirrors	
☒ Cruise Control	
☒ Tilt Wheel	
☐ Sun Roof	
☒ AM FM ☐ CD ☐ DVD	
☐ Amp Subwoofer	
☐ Touch Display	
☒ Leather Seats	
☐ EV Charger	
☐ Breathalyzer	
☐ Trailer Hitch	
☐ Bed Liner	
☐ Step Rails	
☐ Tool Box Locked Yes / No	
☐ Bed Cover or Cap Locked Yes / No	
☐ Hubcaps # _____	
☐ Factory Rims	
☐ Aftermarket Rims	

Completed By _____ Date _____

Comments Leather seats in rear only.

Auction/Dealer Receipt for Repossession

Date _____ Time _____

The undersigned acknowledges receipt of the above described vehicle in identical condition listed above.

Printed Name _____

Signature _____

Witness _____