


Lot Space # _____

Summus Reference No. 348365

Client <u>Chesapeake</u>		Vehicle Info	
Customer Name _____	Year <u>2007</u> Make <u>Ford</u> Color <u>White</u>	Model <u>Five Hundred</u> Doors <u>4</u>	Ebrake: Yes / No _____
Asset # <u>F511</u>	License No. _____ State _____ Exp. Date _____	Mileage <u>123801</u> ☐ Won't Display	Heavy Damage: Yes / No _____
Unit Secured From: <u>956 Greenbrier Parkway Ches</u>			
Date Recovered <u>1/20/26</u>	P/U By <u>984</u> Tow By & Truck # <u>103</u>		
Time: _____ AM or PM			
Storage Address:			
☒ Summus Skip and Collateral Solutions			
2616 Quality Court			
Virginia Beach, VA 23454			
Release Hours By Appointment Only			
VIN <u>1FAFP24117G121650</u>		☒ Ignition <u>2</u> ☐ Transponder ☐ Push Button ☐ No Key ☐ FOB ☐ Keys ☐ Has Keys Does not Run or Start	



MECHANICAL	Engine	☒ OK	☐ Rough	☐ Burns Oil
	Transmission	☒ OK	☐ Slips	☐ Leaks Oil
TIRE	Clutch	☐ OK	☐ Fair	☐ Slips
	Brakes	☒ OK	☐ Fair	☐ Pull Grab
GENERAL	Battery	☒ Yes ☐ No ☒ OK	☐ Dead	☐ Disc..
	Engine Intact:	☒ Yes ☐ No	This condition report was completed by a non mechanic and unit not road tested.	
EQUIPMENT	Good	Fair	Poor	None
	L. Front	☒	☐	☐
L. Rear	☒	☐	☐	☐
	R. Front	☒	☐	☐
R. Rear	☒	☐	☐	☐
	Spare	☐	☐	☐
JACK	☐ Jack	☐ Spare Wheel	☐ Duals	
	Windshield	☒ OK	☐ Crk	☐ Chip
L. Front	☒	☐	☐	☐
	L. Rear	☒	☐	☐
R. Front	☒	☐	☐	☐
	R. Rear	☒	☐	☐
Rearview	☒	☐	☐	☐
	Inst Panel	☒	☐	☐
F. Seats	☒	☐	☐	☐
	R. Seats	☒	☐	☐
Door Panels	☒	☐	☐	☐
	Mat Carpet	☒	☐	☐
Headliner	☒	☐	☐	☐
		☒	☐	☐

Completed By _____

Date _____

Comments fire light on

Auction/Dealer Receipt for Repossession

Date _____ Time _____

The undersigned acknowledges receipt of the above described vehicle in identical condition listed above.

Printed Name _____

Signature _____

Witness _____