

GovDeals

Lot Space #

Summs Reference No

342005

AWD / 4X4

Client City of Chesapeake **Lien Holder**

Customer Name _____

Asset # FQ063

Unit Secured From 956 Greenbrier Pkwy

Vehicle Info
Year 2017 **Make** Freightliner **Color** Red/White
Model m2-106 **Doors** _____ **Ebrake:** Yes / No
License No. _____ **State** _____ **Exp. Date** _____
Mileage 135582 ☐ **Wont Display** **Lasso lock:** Yes / No
Heavy Damage: Yes / No **Airbags Deployed:** Yes / No

Date Recovered 10/23/25 **P/U By** _____ **Tow By & Truck #** _____ **Tow from F or R** _____

Time: 500 AM or PM

Storage Address:
☒ **Summs Ship and Collateral Solutions**
 2616 Quality Court
 Virginia Beach, VA 23454

Release Hours By Appointment Only

Used ☐ **Go Jacks** ☐ **Dolly** ☐ **Roll Back** ☐ **None** ☐ **Shift Lock** ☐

Customer Aware? Yes / No **Able to Get Into Unit?** Yes / No **Insp** 10/25

Vehicle Locked at Time of Repo? Yes / No **Fuel:** E, 1/4, 1/2, 3/4, F

Personals? Yes / No **Glove/Center Box Access** Yes / No **Trunk Access?** Yes / No

Keys? Yes / No **How Many** _____ **How Many FOBS** _____

K ☒ **Ignition** ☐

E ☐ **Transponder** ☐

Y ☐ **Push Button** ☐


S ☐ **No Key** ☐

☐ **FOB** ☐

☒ **Keys** ☐

☐ **Has Keys Does not Run or Start** ☐

VIN 1 F V A C W D T 4 H H H W 6 5 3 3



Completed While
☐ **Sunny** ☐ **Frost on Car** ☐ **Rainy/Wet**
☐ **Snow** ☐ **Ice/Over** ☐ **Night**

General Condition of Collateral
☐ **Good** ☒ **Average** ☐ **Poor**

	Good	Fair	Poor	None
Engine	☒ OK	☐ Rough	☐ Burns Oil	
Transmission	☐ OK	☐ Slips	☐ Leaks Oil	
Clutch	☐ OK	☐ Fair	☐ Slips	
Brakes	☒ OK	☐ Fair	☐ Pull Grab	
Battery	☒ Yes	☐ No	☒ OK	☐ Dead ☐ Disc..
Engine Intact?	☒ Yes	☐ No	This condition report was completed by a non mechanic and unit not road tested.	

EQUIPMENT

☒ A/C	☐ Rear A/C
☐ Auto Trans	☐ 3rd Row
☐ Manual Trans	☐ Navigation
☒ Power Steering	☐ Backup Camera
☒ Power Brakes	☐ Heated Seats
☒ Power Windows	☐ Coated Seats
☐ Power Seats	
☒ Power Door Locks	
☒ Power Mirrors	
☒ Cruise Control	
☒ Tilt Wheel	
☐ Sun Roof	
☒ AM FM ☒ CD ☐ DVD	
☐ Amp Subwoofer	
☐ Touch Display	
☐ Leather Seats	
☐ EV Charger	
☐ Breathalyzer	
☐ Trailer Hitch	
☐ Bed Liner	
☐ Step Rails	
☐ Tool Box Locked Yes / No	
☐ Bed Cover or Cap Locked Yes / No	
☐ Hubcaps #	
☐ Factory Rims	
☐ Aftermarket Rims	

TIRE

	Good	Fair	Poor	None
L. Front	☒			
L. Rear	☒			
R. Front	☒			
R. Rear	☒			
Spare				

☐ **Jack** ☐ **Spare Wheel** ☐ **Duals**

GLASS

	OK	Crk	Chip	Missing
Windshield	☒			
L. Front	☒			
L. Rear	☒			
R. Front	☒			
R. Rear	☒			
Rearview	☒			

INTERIOR

	Good	Fair	Poor	None
Inst Panel	☒			
F. Seats				
R. Seats				
Door Panels				
Mat Carpet				
Headliner	☒			

Completed By

Date

Comments Seats worn/ben
low on DEF
Check engine light on

Auction/Dealer Receipt for Repossession

Date _____ Time _____

The undersigned acknowledges receipt of the above described vehicle in identical condition listed above.

Printed Name _____

Signature _____

Witness _____