


Lot Space # _____

Summis Reference No 342006

Client <u>City of Chesapeake</u>		Vehicle Info	
Customer Name _____		Year <u>2013</u> Make <u>Toro</u> Color <u>Red</u>	
Asset # <u>P105</u>		Model <u>Piding Sandpiper</u> Doors _____ Ebrake: Yes / No	
Unit Secured From <u>956 Greenbrier Pkwy</u>		License No. _____ State _____ Exp. Date _____	
Date Recovered <u>10/23/25</u>		Mileage _____ ☐ Won't Display Lasso lock: Yes / No	
Time: <u>5:00</u> AM or PM		Heavy Damage: Yes / No Airbags Deployed: Yes / No	
Storage Address: Summis Skip and Collateral Solutions 2616 Quality Court Virginia Beach, VA 23454		P/U By <u>977</u> Tow By & Truck # <u>103</u> Tow from F or R Used ☐ Go Jacks ☐ Dolly ☐ Roll Back ☐ None ☐ Shift Lock Customer Aware? <u>Yes/No</u> Able to Get Into Unit? <u>Yes/No</u> Insp Vehicle Locked at Time of Repo? <u>Yes/No</u> Fuel: E, 1/4, 1/2, 3/4, F Personals? <u>Yes/No</u> Glove/Center Box Access <u>Yes/No</u> Trunk Access? <u>Yes/No</u> Keys? <u>Yes/No</u> How Many _____ How Many FOBS _____	
Release Hours By Appointment Only		K ☐ Ignition E ☐ Transponder V ☐ Push Button S ☐ No Key ☐ FOB ☐ Keys ☐ Has Keys Does not Run or Start	
VIN		<u>3 1 3 0 0 0 5 1 3</u>	



Completed While

☐ Sunny ☐ Frost on Car ☐ Rainy/Wet
☐ Snow ☐ Ice Over ☐ Night

General Condition of Collateral

☐ Good ☐ Average ☐ Poor

M E C H A N I C A L	Engine	☒ OK	☐ Rough	☐ Burns Oil	
	Transmission	☒ OK	☐ Slips	☐ Leaks Oil	
	Clutch	☐ OK	☐ Fair	☐ Slips	
	Brakes	☐ OK	☒ Fair	☐ Pull Grab	
	Battery	☒ Yes ☐ No	☒ OK	☐ Dead ☐ Disc..	
Engine Intact ☒ Yes ☐ No This condition report was completed by a non mechanic and unit not road tested.					
T I R E S	L. Front	☒ Good	☐ Fair	☐ Poor	☐ None
	L. Rear	☐ Good	☒ Fair	☐ Poor	☐ None
	R. Front	☐ Good	☒ Fair	☐ Poor	☐ None
	R. Rear	☐ Good	☒ Fair	☐ Poor	☐ None
	Spare	☐ Good	☐ Fair	☐ Poor	☐ None
G L A S S	Windshield	☒ OK	☐ Crk	☐ Chip	☐ Missing
	L. Front	☐ OK	☐ Crk	☐ Chip	☐ Missing
	L. Rear	☐ OK	☐ Crk	☐ Chip	☐ Missing
	R. Front	☐ OK	☐ Crk	☐ Chip	☐ Missing
	R. Rear	☐ OK	☐ Crk	☐ Chip	☐ Missing
I N T E R I O R	Inst Panel	☒ Good	☐ Fair	☐ Poor	☐ None
	F. Seats	☐ Good	☒ Fair	☐ Poor	☐ None
	R. Seats	☐ Good	☒ Fair	☐ Poor	☐ None
	Door Panels	☐ Good	☐ Fair	☐ Poor	☐ None
	Mat Carpet	☐ Good	☐ Fair	☐ Poor	☐ None
Headliner					

EQUIPMENT

- | | |
|---|--|
| ☐ A/C | ☐ Rear A/C |
| ☐ Auto Trans | ☐ 3rd Row |
| ☐ Manual Trans | ☐ Navigation |
| ☐ Power Steering | ☐ Backup Camera |
| ☐ Power Brakes | ☐ Heated Seats |
| ☐ Power Windows | ☐ Coated Seats |
| ☐ Power Seats | |
| ☐ Power Door Locks | |
| ☐ Power Mirrors | |
| ☐ Cruise Control | |
| ☐ Tilt Wheel | |
| ☐ Sun Roof | |
| ☐ AM FM ☐ CD ☐ DVD | |
| ☐ Amp Subwoofer | |
| ☐ Touch Display | |
| ☐ Leather Seats | |
| ☐ EV Charger | |
| ☐ Breathalyzer | |
| ☐ Trailer Hitch | |
| ☐ Bed Liner | |
| ☐ Step Rails | |
| ☐ Tool Box Locked Yes / No | |
| ☐ Bed Cover or Cap Locked Yes / No | |
| ☐ Hubcaps # _____ | |
| ☐ Factory Rims | |
| ☐ Aftermarket Rims | |

Completed By _____

Date _____

Comments _____

Auction/Dealer Receipt for Repossession

Date _____ Time _____

The undersigned acknowledges receipt of the above described vehicle in identical condition listed above.

Printed Name _____

Signature _____

Witness _____