


Lot Space # _____

Summa Reference No 342010

Client <u>City of Chesapeake</u>	Vehicle Info Year <u>2018</u> Make <u>Toro</u> Color <u>red</u>	
Customer Name _____	Model <u>72" Z mower</u> Doors _____	Ebrake: Yes / No _____
Asset # <u>PLO70</u>	License No. _____ State _____	Exp. Date _____
Unit Secured From <u>956 Greenbrier Pkwy</u>	Mileage _____ ☐ Won't Display	Lasso lock: Yes / No _____
	Heavy Damage: Yes / No _____	Airbags Deployed: Yes / No _____
Date Recovered <u>10/23/25</u>	P/U By _____ Tow By & Truck # _____	Tow from F or R _____
Time: <u>5:00</u> AM or PM _____	Used ☐ Go Jacks ☐ Dolly ☐ Roll Back ☐ None ☐ Shift Lock	
Storage Address: ☒ Summa Skip and Collateral Solutions 2616 Quality Court Virginia Beach, VA 23454	Customer Aware? <u>Yes/No</u> Able to Get Into Unit? <u>Yes/No</u> Insp _____	
Release Hours By Appointment Only	Vehicle Locked at Time of Repo? <u>Yes/No</u> Fuel: E, 1/4, 1/2, 3/4, F _____	
	Personals? <u>Yes/No</u> Glove/Center Box Access <u>Yes/No</u> Trunk Access? <u>Yes/No</u>	
	Keys? <u>Yes/No</u> How Many _____ How Many FOBS _____	
		☐ Ignition ☐ Transponder ☐ Push Button ☐ No Key ☐ FOB ☐ Keys ☐ Has Keys Does not Run or Start
VIN	4 0 3 3 1 9 9 3 1	



Completed While

☐ Sunny ☐ Frost on Car ☐ Rainy/Wet
☐ Snow ☐ Ice Over ☐ Night

General Condition of Collateral

☐ Good ☐ Average ☐ Poor

M E C H A N I C A L	Engine	☒ OK	☐ Rough	☐ Burns Oil
	Transmission	☒ OK	☐ Slips	☐ Leaks Oil
	Clutch	☐ OK	☐ Fair	☐ Slips
	Brakes	☒ OK	☐ Fair	☐ Pull Grab
	Battery	☒ Yes ☐ No	☐ OK	☐ Dead ☐ Disc..
Engine Intact? ☒ Yes ☐ No This condition report was completed by a non mechanic and unit not road tested.				
T I R E S	Good	Fair	Poor	None
	L. Front			
	L. Rear			
	R. Front			
	R. Rear			
Spare ☐ Jack ☐ Spare Wheel ☐ Duals				
G L A S S	OK	Crk	Chip	Missing
	Windshield			
	L. Front			
	L. Rear			
	R. Front			
I N T E R I O R	Good	Fair	Poor	None
	Inst Panel			
	F. Seats			
	R. Seats			
	Door Panels			
Mat Carpet ☐ Headliner ☐				

EQUIPMENT

- | | |
|---|--|
| ☐ A/C | ☐ Rear A/C |
| ☐ Auto Trans | ☐ 3rd Row |
| ☐ Manual Trans | ☐ Navigation |
| ☐ Power Steering | ☐ Backup Camera |
| ☐ Power Brakes | ☐ Heated Seats |
| ☐ Power Windows | ☐ Coated Seats |
| ☐ Power Seats | |
| ☐ Power Door Locks | |
| ☐ Power Mirrors | |
| ☐ Cruise Control | |
| ☐ Tilt Wheel | |
| ☐ Sun Roof | |
| ☐ AM FM ☐ CD ☐ DVD | |
| ☐ Amp Subwoofer | |
| ☐ Touch Display | |
| ☐ Leather Seats | |
| ☐ EV Charger | |
| ☐ Breathalyzer | |
| ☐ Trailer Hitch | |
| ☐ Bed Liner | |
| ☐ Step Rails | |
| ☐ Tool Box Locked Yes / No | |
| ☐ Bed Cover or Cap Locked Yes / No | |
| ☐ Hubcaps # _____ | |
| ☐ Factory Rims | |
| ☐ Aftermarket Rims | |

Completed By _____

Date _____

Comments _____

Auction/Dealer Receipt for Repossession

Date _____ Time _____

The undersigned acknowledges receipt of the above described vehicle in identical condition listed above.

Printed Name _____

Signature _____

Witness _____