


Lot Space # _____ Summis Reference No 342011

Client <u>City of Chesapeake</u> Lien Holder		Vehicle Info	
Customer Name _____		Year <u>2004</u> Make <u>John Deere</u> Color <u>green</u>	
Asset # <u>PL173</u>		Model <u>Tractor</u> Doors _____ Ebrake: Yes / No	
Unit Secured From <u>956 Greenbrier Pkwy</u>		License No. _____ State _____ Exp. Date _____	
Date Recovered <u>10/23/25</u> P/U By <u>971</u> Tow By & Truck # <u>104</u> Tow from F or R		Mileage <u>55.1 hrs</u> ☐ Won't Display Lasso lock: Yes / No	
Time: <u>1100</u> AM or PM		Heavy Damage: Yes / No	Airbags Deployed: Yes / No
Storage Address: ☒ Summis Skip and Collateral Solutions 2616 Quality Court Virginia Beach, VA 23454		☐ Ignition ☐ Transponder ☐ Push Button ☐ No Key ☐ FOB ☐ Keys ☐ Has Keys Does not Run or Start	
Release Hours By Appointment Only		Customer Aware? <u>Yes/No</u> Able to Get Into Unit? <u>Yes/No</u> Insp _____ Vehicle Locked at Time of Repo? <u>Yes/No</u> Fuel: E, 1/4, 1/2, 3/4, F Personals? <u>Yes/No</u> Glove/Center Box Access <u>Yes/No</u> Trunk Access? <u>Yes/No</u> Keys? <u>Yes/No</u> How Many _____ How Many FOBS _____	
VIN <u>LJ55LN5320S432880</u>			



Completed While
☐ Sunny ☐ Frost on Car ☐ Rainy/Wet
☐ Snow ☐ Ice Over ☐ Night

General Condition of Collateral
☐ Good ☐ Average ☐ Poor

M E C H A N I C A L	Engine	☒ OK	☐ Rough	☐ Burns Oil	
	Transmission	☒ OK	☐ Slips	☐ Leaks Oil	
	Clutch	☐ OK	☐ Fair	☐ Slips	
	Brakes	☐ OK	☒ Fair	☐ Pull Grab	
	Battery	☒ Yes ☐ No	☐ OK	☐ Dead ☐ Disc..	
Engine Intact: ☒ Yes ☐ No This condition report was completed by a non mechanic and unit not road tested.					
T I R E S	L. Front	☒ Good	☐ Fair	☐ Poor	☐ None
	L. Rear	☐ Good	☒ Fair	☐ Poor	☐ None
	R. Front	☐ Good	☒ Fair	☐ Poor	☐ None
	R. Rear	☐ Good	☒ Fair	☐ Poor	☐ None
	Spare	☐ Good	☐ Fair	☐ Poor	☐ None
G L A S S	Windshield	☒ OK	☐ Crk	☐ Chip	☐ Missing
	L. Front	☐ OK	☐ Crk	☐ Chip	☐ Missing
	L. Rear	☐ OK	☐ Crk	☐ Chip	☐ Missing
	R. Front	☐ OK	☐ Crk	☐ Chip	☐ Missing
	R. Rear	☐ OK	☐ Crk	☐ Chip	☐ Missing
I N T E R I O R	Inst Panel	☒ Good	☐ Fair	☐ Poor	☐ None
	F. Seats	☐ Good	☐ Fair	☐ Poor	☐ None
	R. Seats	☐ Good	☐ Fair	☐ Poor	☐ None
	Door Panels	☐ Good	☐ Fair	☐ Poor	☐ None
	Mat Carpet	☐ Good	☐ Fair	☐ Poor	☐ None
E Q U I P M E N T	☐ Jack	☐ Spare Wheel	☐ Duals		
	☐ A/C	☐ Auto Trans	☐ Manual Trans	☐ Power Steering	☐ Power Brakes
	☐ Rear A/C	☐ 3rd Row	☐ Navigation	☐ Backup Camera	☐ Heated Seats
	☐ Cruise Control	☐ Tilt Wheel	☐ Sun Roof	☐ AM FM ☐ CD ☐ DVD	☐ Amp Subwoofer
	☐ Power Door Locks	☐ Power Mirrors	☐ Touch Display	☐ Leather Seats	☐ Coated Seats
	☐ Power Seats	☐ Power Windows	☐ Power Seats	☐ Power Door Locks	☐ Power Mirrors
	☐ EV Charger	☐ Breathalyzer	☐ Trailer Hitch	☐ Bed Liner	☐ Step Rails
	☐ Tool Box	☐ Locked Yes / No	☐ Bed Cover or Cap	☐ Locked Yes / No	☐ Hubcaps # _____
	☐ Factory Rims	☐ Aftermarket Rims			

Completed By _____ Date _____

Comments _____

Auction/Dealer Receipt for Repossession

Date _____ Time _____

The undersigned acknowledges receipt of the above described vehicle in identical condition listed above.

Printed Name _____

Signature _____

Witness _____