


Lot Space # _____

Summis Reference No 342012

Client <u>City of Chesapeake</u>	Lien Holder	Vehicle Info	Year <u>2013</u> Make <u>Dodge</u> Color <u>White</u>
Customer Name _____		Model <u>Charger</u> Doors _____	Ebrake: Yes / No _____
Asset # <u>SD090</u>		License No. _____ State _____	Exp. Date _____
Unit Secured From <u>956 Greenbrier Pkwy</u>		Mileage <u>82826</u> ☐ Won't Display	Lasso lock: Yes / No _____
		Heavy Damage: Yes / No _____	Airbags Deployed: Yes / No _____
Date Recovered <u>10/22/25</u>	P/U By <u>971</u>	Tow By & Truck # <u>104</u>	Tow from F or R _____
Time: <u>430</u> AM or PM <u>PM</u>	Used ☐ Go Jacks ☐ Dolly ☐ Roll Back ☐ None ☐ Shift Lock	Customer Aware? <u>Yes/No</u>	Able to Get Into Unit? <u>Yes/No</u> Insp _____
Storage Address: ☒ Summis Skip and Collateral Solutions 2616 Quality Court Virginia Beach, VA 23454	Vehicle Locked at Time of Repo? <u>Yes/No</u>	Fuel: E, 1/4, 1/2, 3/4, F _____	Personals? <u>Yes/No</u> Glove/Center Box Access <u>Yes/No</u> Trunk Access? <u>Yes/No</u>
Release Hours By Appointment Only	Keys? <u>Yes/No</u> How Many _____	How Many FOBS _____	
VIN <u>2C4RDGBG4DR609862</u>			



Completed While _____

General Condition of Collateral _____

Completed While _____

General Condition of Collateral _____

M E C H A N I C A L	Engine ☒ OK ☐ Rough ☐ Burns Oil	Transmission ☒ OK ☐ Slips ☐ Leaks Oil	Clutch ☐ OK ☐ Fair ☐ Slips	Brakes ☐ OK ☒ Fair ☐ Pull Grab	Battery ☒ Yes ☐ No ☒ OK ☐ Dead ☐ Disc..	Engine Intact ☐ Yes ☐ No	This condition report was completed by a non mechanic and unit not road tested.			
T I R E S	☒ L. Front	Good	Fair	Poor	None	EQUIPMENT				
G L A S S	☒ L. Rear	Good	Fair	Poor	None	☐ A/C	☐ Rear A/C	☐ 3rd Row	☐ Navigation	
I N T E R I O R	☒ R. Front	Good	Fair	Poor	None	☐ Manual Trans	☐ Power Steering	☐ Backup Camera	☐ Heated Seats	
	☒ R. Rear	Good	Fair	Poor	None	☐ Power Brakes	☐ Power Windows	☐ Power Seats	☐ Power Door Locks	
	☒ Spare	Good	Fair	Poor	None	☐ Power Mirrors	☐ Cruise Control	☐ Tilt Wheel	☐ Sun Roof	
	☒ Jack	Good	Fair	Poor	None	☐ AM FM	☐ CD	☐ DVD	☐ Amp	
	☒ Windshield	Good	Fair	Poor	None	☐ Touch Display	☐ Leather Seats	☐ EV Charger	☐ Breathalyzer	
	☒ L. Front	Good	Fair	Poor	None	☐ Trailer Hitch	☐ Bed Liner	☐ Step Rails	☐ Tool Box	
	☒ L. Rear	Good	Fair	Poor	None	☐ Bed Cover or Cap	☐ Locked Yes / No	☐ Hubcaps # _____	☐ Factory Rims	
	☒ R. Front	Good	Fair	Poor	None	☐ Aftermarket Rims				
	☒ R. Rear	Good	Fair	Poor	None					
	☒ Rearview	Good	Fair	Poor	None					
	☒ Inst Panel	Good	Fair	Poor	None					
	☒ F. Seats	Good	Fair	Poor	None					
	☒ R. Seats	Good	Fair	Poor	None					
	☒ Door Panels	Good	Fair	Poor	None					
	☒ Mat Carpet	Good	Fair	Poor	None					
	☒ Headliner	Good	Fair	Poor	None					

Completed By _____

Date _____

Comments _____

Auction/Dealer Receipt for Repossession

Date _____ Time _____

The undersigned acknowledges receipt of the above described vehicle in identical condition listed above.

Printed Name _____

Signature _____

Witness _____