


Lot Space # _____ Summs Reference No. 348376

Client <u>Chesapeake</u>	Vehicle Info
Customer Name _____	Year <u>2014</u> Make <u>Ford</u> Color <u>WHITE</u>
Asset # <u>SD092</u>	Model <u>Fusion</u> Doors <u>4</u> Ebrake: Yes / No
Unit Secured From <u>956 Greenbrier Pkwy Ches</u>	License No. _____ State _____ Exp. Date _____
	Mileage <u>90910</u> ☐ Won't Display
	Heavy Damage: Yes / No

Date Recovered <u>1/22/26</u>	P/U By <u>807</u> Tow By & Truck # <u>132</u>
Time: <u>11:00</u> AM or PM	
Storage Address:	
☐ Summs Skip and Collateral Solutions	
2616 Quality Court	
Virginia Beach, VA 23454	
Release Hours By Appointment Only	

K ☒ Ignition	
E ☒ Transponder	
Y ☐ Push Button	
S ☐ No Key	
☐ FOB	
☒ Keys	<u>3</u>
☐ Has Keys Does not Run or Start	

VIN 3FA6POLUTER212962



Completed While
☒ Sunny ☐ Frost on Car ☐ Rainy/Wet
☐ Snow ☐ Iced Over ☐ Night

General Condition of Collateral
☐ Good ☒ Average ☐ Poor

M E C H A N I C A L	Engine	☒ OK	☐ Rough	☐ Burns Oil	
	Transmission	☒ OK	☐ Slips	☐ Leaks Oil	
	Clutch	☐ OK	☐ Fair	☐ Slips	
	Brakes	☐ OK	☒ Fair	☐ Pull Grab	
	Battery	☒ Yes ☐ No	☐ OK	☐ Dead ☐ Disc..	
Engine Intact: ☐ Yes ☐ No This condition report was completed by a non mechanic and unit not road tested.					
T I R E S	L. Front	☒ Good	☐ Fair	☐ Poor	☐ None
	L. Rear	☐ Good	☐ Fair	☐ Poor	☐ None
	R. Front	☐ Good	☐ Fair	☐ Poor	☐ None
	R. Rear	☐ Good	☐ Fair	☐ Poor	☐ None
	Spare	☐ Good	☐ Fair	☐ Poor	☐ None
G L A S S	Windshield	☒ OK	☐ Crk	☐ Chip	☐ Missing
	L. Front	☐ OK	☐ Crk	☐ Chip	☐ Missing
	L. Rear	☐ OK	☐ Crk	☐ Chip	☐ Missing
	R. Front	☐ OK	☐ Crk	☐ Chip	☐ Missing
	R. Rear	☐ OK	☐ Crk	☐ Chip	☐ Missing
I N T E R I O R	Inst Panel	☒ Good	☐ Fair	☐ Poor	☐ None
	F. Seats	☐ Good	☐ Fair	☐ Poor	☐ None
	R. Seats	☐ Good	☐ Fair	☐ Poor	☐ None
	Door Panels	☐ Good	☐ Fair	☐ Poor	☐ None
	Mat Carpet	☐ Good	☐ Fair	☐ Poor	☐ None
E Q U I P M E N T	Headliner	☐ Good	☐ Fair	☐ Poor	☐ None
	A/C	☒ A/C	☐ Rear A/C	☐ 3rd Row	☐ Navigation
	Auto Trans	☐ Manual Trans	☐ Power Steering	☐ Backup Camera	☐ Heated Seats
	Power Brakes	☐ Power Windows	☐ Power Seats	☐ Power Door Locks	☐ Power Mirrors
	Power Seats	☐ Power Door Locks	☐ Power Mirrors	☐ Cruise Control	☐ Tire Wheel
I N T E R I O R	Sun Roof	☐ AM FM ☐ CD ☐ DVD	☐ Amp Subwoofer	☐ Touch Display	☐ Leather Seats
	EV Charger	☐ Breathalyzer	☐ Trailer Hitch	☐ Bed Liner	☐ Step Rails
	Tool Box	☐ Locked Yes / No	☐ Bed Cover or Cap	☐ Locked Yes / No	☐ Hubcaps # _____
	Factory Rims	☐ Aftermarket Rims			

Completed By 904 Date 1/22/26

Comments _____

Auction/Dealer Receipt for Repossession

Date _____ Time _____

The undersigned acknowledges receipt of the above described vehicle in identical condition listed above.

Printed Name _____

Signature _____

Witness _____