


Lot Space # _____ Summary Reference No 342014

Client <u>City of Chesapeake</u> Lien Holder		Vehicle Info	
Customer Name _____		Year <u>2011</u> Make <u>Ford</u> Color <u>White</u>	
Asset # <u>US3005</u>		Model <u>E350</u> Doors _____ Ebrake: Yes / No	
Unit Secured From <u>956 Greenbrier Pkwy</u>		License No. _____ State _____ Exp. Date _____	
Date Recovered <u>10/22/25</u>		Mileage <u>116683</u> ☐ Won't Display Lasso lock: Yes / No	
Time: <u>3:00</u> AM or PM		Heavy Damage: Yes / No	Airbags Deployed: Yes / No
Storage Address: ☒ Summa Skip and Collateral Solutions 2616 Quality Court Virginia Beach, VA 23454		P/U By <u>971</u> Tow By & Truck # <u>104</u> Tow from F or R Used ☐ Go Jacks ☐ Dolly ☐ Roll Back ☐ None ☐ Shift Lock Customer Aware? <u>Yes/No</u> Able to Get Into Unit? <u>Yes/No</u> Insp Vehicle Locked at Time of Repo? <u>Yes/No</u> Fuel: E, 1/4, 1/2, 3/4, F Personals? <u>Yes/No</u> Glove/Center Box Access <u>Yes/No</u> Trunk Access? <u>Yes/No</u> Keys? <u>Yes/No</u> How Many _____ How Many FOBS _____	
Release Hours By Appointment Only		☐ Ignition <u>4</u> ☐ Transponder ☐ Push Button ☐ No Key ☐ FOB ☐ Keys ☐ Has Keys Does not Run or Start	
VIN <u>1FDWE3FL8BD B30209</u>			



M E C H A N I C A L	Engine	☒ OK	☐ Rough	☐ Burns Oil	
	Transmission	☒ OK	☐ Slips	☐ Leaks Oil	
	Clutch	☐ OK	☐ Fair	☐ Slips	
	Brakes	☐ OK	☒ Fair	☐ Pull Grab	
	Battery	☒ Yes ☐ No ☒ OK	☐ Dead	☐ Disc..	
	Engine Intact:	☒ Yes ☐ No	This condition report was completed by a non mechanic and unit not road tested.		
T I R E S	L. Front	☒ Good	☐ Fair	☐ Poor	☐ None
	L. Rear	☐ Good	☒ Fair	☐ Poor	☐ None
	R. Front	☐ Good	☒ Fair	☐ Poor	☐ None
	R. Rear	☐ Good	☒ Fair	☐ Poor	☐ None
	Spare	☐ Good	☐ Fair	☐ Poor	☐ None
	Jack	☐ OK	☐ Crk	☐ Chip	☐ Missing
G L A S S	Windshield	☒ OK	☐ Crk	☐ Chip	☐ Missing
	L. Front	☐ Good	☒ Fair	☐ Poor	☐ None
	L. Rear	☐ Good	☒ Fair	☐ Poor	☐ None
	R. Front	☐ Good	☒ Fair	☐ Poor	☐ None
	R. Rear	☐ Good	☒ Fair	☐ Poor	☐ None
	Rearview	☐ Good	☒ Fair	☐ Poor	☐ None
I N T E R I O R	Inst Panel	☒ Good	☐ Fair	☐ Poor	☐ None
	F. Seats	☐ Good	☒ Fair	☐ Poor	☐ None
	R. Seats	☐ Good	☒ Fair	☐ Poor	☐ None
	Door Panels	☐ Good	☒ Fair	☐ Poor	☐ None
	Mat Carpet	☐ Good	☒ Fair	☐ Poor	☐ None
	Headliner	☐ Good	☒ Fair	☐ Poor	☐ None

Completed While
☒ Sunny ☐ Frost on Car ☐ Rainy/Wet
☐ Snow ☐ Ice Over ☐ Night
 General Condition of Collateral
☐ Good ☒ Average ☐ Poor

EQUIPMENT

- ☐ A/C
- ☐ Rear A/C
- ☐ Auto Trans
- ☐ 3rd Row
- ☐ Manual Trans
- ☐ Navigation
- ☐ Power Steering
- ☐ Backup Camera
- ☐ Power Brakes
- ☐ Heated Seats
- ☐ Power Windows
- ☐ Cooled Seats
- ☐ Power Seats
- ☐ Power Door Locks
- ☐ Power Mirrors
- ☐ Cruise Control
- ☐ Tilt Wheel
- ☐ Sun Roof
- ☐ AM FM ☐ CD ☐ DVD
- ☐ Amp Subwoofer
- ☐ Touch Display
- ☐ Leather Seats
- ☐ EV Charger
- ☐ Breathalyzer
- ☐ Trailer Hitch
- ☐ Bed Liner
- ☐ Step Rails
- ☐ Tool Box Locked Yes / No
- ☐ Bed Cover or Cap Locked Yes / No
- ☐ Hubcaps # _____
- ☐ Factory Rims
- ☐ Aftermarket Rims

Completed By _____ Date _____

Comments _____

Auction/Dealer Receipt for Repossession

Date _____ Time _____

The undersigned acknowledges receipt of the above described vehicle in identical condition listed above.

Printed Name _____

Signature _____

Witness _____