


Lot Space # _____ Summs Reference No. 348377

Client <u>Chesapeake</u> Customer Name _____ Asset # <u>US514</u> Unit Secured From <u>956 Greenbrier Pkwy Ches</u>	Vehicle Info Year <u>2012</u> Make <u>Ford</u> Color <u>White</u> Model <u>F350</u> Doors _____ Ebrake: Yes / No License No. _____ State _____ Exp. Date _____ Mileage <u>253268</u> ☐ Won't Display Heavy Damage: Yes / No
Date Recovered <u>1/21/26</u> Time: _____ AM or PM Storage Address: ☒ Summs Skip and Collateral Solutions 2616 Quality Court Virginia Beach, VA 23454 Release Hours By Appointment Only	P/U By <u>971</u> Tow By & Truck # <u>104</u>
VIN <u>1F8X3C69CEC12764</u>	



Completed While
☒ Sunny ☐ Frost on Car ☐ Rainy/Wet
☐ Snow ☐ Ice Over ☐ Night

General Condition of Collateral
☐ Good ☐ Average ☐ Poor

M E C H A N I C A L	Engine	☒ OK	☐ Rough	☐ Burns Oil	
	Transmission	☒ OK	☐ Slips	☐ Leaks Oil	
	Clutch	☐ OK	☐ Fair	☐ Slips	
	Brakes	☐ OK	☒ Fair	☐ Pull Grab	
	Battery	☒ Yes ☐ No	☒ OK	☐ Dead ☐ Disc...	
Engine Intact		☒ Yes ☐ No	This condition report was completed by a non mechanic and unit not road tested.		
T I R E S	L. Front	☒ Good	☐ Fair	☐ Poor	☐ None
	L. Rear	☐ Good	☒ Fair	☐ Poor	☐ None
	R. Front	☐ Good	☒ Fair	☐ Poor	☐ None
	R. Rear	☐ Good	☒ Fair	☐ Poor	☐ None
	Spare	☐ Good	☐ Fair	☐ Poor	☐ None
G L A S S	Windshield	☒ OK	☐ Crk	☐ Chip	☐ Missing
	L. Front	☐ OK	☒ Crk	☐ Chip	☐ Missing
	L. Rear	☐ OK	☒ Crk	☐ Chip	☐ Missing
	R. Front	☐ OK	☒ Crk	☐ Chip	☐ Missing
	R. Rear	☐ OK	☒ Crk	☐ Chip	☐ Missing
I N T E R I O R	Inst Panel	☒ Good	☐ Fair	☐ Poor	☐ None
	F. Seats	☐ Good	☒ Fair	☐ Poor	☐ None
	R. Seats	☐ Good	☒ Fair	☐ Poor	☐ None
	Door Panels	☐ Good	☒ Fair	☐ Poor	☐ None
	Mat Carpet	☐ Good	☒ Fair	☐ Poor	☐ None
Headliner	☐ Good	☒ Fair	☐ Poor	☐ None	

EQUIPMENT

☐ A/C	☐ Rear A/C
☐ Auto Trans	☐ 3rd Row
☐ Manual Trans	☐ Navigation
☐ Power Steering	☐ Backup Camera
☐ Power Brakes	☐ Heated Seats
☐ Power Windows	☐ Cooled Seats
☐ Power Seats	
☐ Power Door Locks	
☐ Power Mirrors	
☐ Cruise Control	
☐ Nit Wheel	
☐ Sun Roof	
☐ AM FM ☐ CD ☐ DVD	
☐ Amp. Subwoofer	
☐ Touch Display	
☐ Leather Seats	
☐ EV Charger	
☐ Breathalyzer	
☐ Trailer Hitch	
☐ Bed Liner	
☐ Step Rails	
☐ Tool Box Locked Yes / No	
☐ Bed Cover or Cap Locked Yes / No	
☐ Hubcaps # _____	
☒ Factory Rims	
☐ Aftermarket Rims	

Completed By _____ Date _____

Comments driver seat ripped

Auction/Dealer Receipt for Repossession

Date _____ Time _____

The undersigned acknowledges receipt of the above described vehicle in identical condition listed above.

Printed Name _____

Signature _____

Witness _____