


Lot Space # _____ Summs Reference No. 348379

Client <u>Chesapeake</u> Customer Name _____ Asset # <u>Y105A</u> Unit Secured From <u>256 Greenbrier Pkwy Ches</u>		Vehicle Info Year <u>2008</u> Make <u>Enclosed</u> Color _____ Model <u>Trailer</u> Doors _____ Ebrake: Yes / No License No. _____ State _____ Exp. Date _____ Mileage <u>N/A</u> ☐ Won't Display Heavy Damage: Yes / No	
Date Recovered <u>1/23/26</u> Time: _____ AM or PM Storage Address: ☐ Summs Skip and Collateral Solutions 2616 Quality Court Virginia Beach, VA 23454 Release Hours By Appointment Only		P/U By <u>807</u> Tow By & Truck # <u>132</u>	
		K ☐ Ignition E ☐ Transponder Y ☐ Push Button S ☒ No Key ☐ FOB ☐ Keys ☐ Has Keys Does not Run or Start	
VIN <u>4 F P F B 1 2 2 3 8 G 1 2 4 1 2 4</u>			



Completed While
☐ Sunny ☐ Frost on Car ☐ Rainy/Wet
☐ Snow ☐ Ice Over ☐ Night

General Condition of Collateral
☐ Good ☐ Average ☐ Poor

M E C H A N I C A L	Engine	☐ OK	☐ Rough	☐ Burns Oil
	Transmission	☐ OK	☐ Slips	☐ Leaks Oil
	Clutch	☐ OK	☐ Fair	☐ Slips
	Brakes	☐ OK	☐ Fair	☐ Pull Grab
	Battery	☒ Yes ☐ No	☐ OK	☒ Dead ☐ Disc..
Engine Intact: ☐ Yes ☐ No This condition report was completed by a non mechanic and unit not road tested.				
T I R E S	☒ Good	☒ Fair	☐ Poor	☐ None
	L. Front	☒	☐	☐
	L. Rear	☒	☐	☐
	R. Front	☒	☐	☐
	R. Rear	☒	☐	☐
G L A S S	☒ OK	☐ Crk	☐ Chip	☐ Missing
	Windshield	☐	☐	☐
	L. Front	☐	☐	☐
	L. Rear	☐	☐	☐
	R. Front	☐	☐	☐
I N T E R I O R	☒ Good	☐ Fair	☐ Poor	☐ None
	Inst Panel	☐	☐	☐
	F. Seats	☐	☐	☐
	R. Seats	☐	☐	☐
	Door Panels	☐	☐	☐
Mat Carpet ☐ Headliner ☐				

EQUIPMENT

☐ A/C	☐ Rear A/C
☐ Auto Trans	☐ 3rd Row
☐ Manual Trans	☐ Navigation
☐ Power Steering	☐ Backup Camera
☐ Power Brakes	☐ Heated Seats
☐ Power Windows	☐ Cooled Seats
☐ Power Seats	
☐ Power Door Locks	
☐ Power Mirrors	
☐ Cruise Control	
☐ Tilt Wheel	
☐ Sun Roof	
☐ AM FM ☐ CD ☐ DVO	
☐ Amp Subwoofer	
☐ Touch Display	
☐ Leather Seats	
☐ EV Charger	
☐ Breathalyzer	
☐ Trailer Hitch	
☐ Bed Liner	
☐ Step Rails	
☐ Tool Box Locked Yes / No	
☐ Bed Cover or Cap Locked Yes / No	
☐ Hubcaps # _____	
☐ Factory Rims	
☐ Aftermarket Rims	

Completed By _____ Date _____

Comments Side Door Latch Loose
Rust & Scratches All Over
Rims Rusty

Auction/Dealer Receipt for Repossession

Date _____ Time _____

The undersigned acknowledges receipt of the above described vehicle in identical condition listed above.

Printed Name _____

Signature _____

Witness _____