


Lot Space # _____ Summa Reference No 342018

Client <u>City of Chesapeake</u>	Lien Holder _____	Vehicle info Year <u>2005</u> Make <u>Bobcat</u> Color <u>white/orange</u>
Customer Name _____	Model <u>skid loader</u> Doors _____	Ebrake: Yes / No
Asset # <u>YH024</u>	License No. _____ State _____	Exp. Date _____
Unit Secured From <u>956 Greenbrier Pkwy</u>	Mileage _____	☐ Won't Display Lasso lock: Yes / No
Date Recovered <u>10/22/25</u>	P/U By <u>971</u> Tow By & Truck # <u>104</u>	Tow from For R _____
Time: <u>5:00</u> AM or PM	Used ☐ Go Jacks ☐ Dolly ☐ Roll Back ☐ None ☐ Shift Lock	
Storage Address: ☐ Summa Skip and Collateral Solutions 2616 Quality Court Virginia Beach, VA 23454	Customer Aware? <u>Yes/No</u> Able to Get Into Unit? <u>Yes/No</u> Insp _____	
Release Hours By Appointment Only	Vehicle Locked at Time of Repo? <u>Yes/No</u> Fuel: E, 1/4, 1/2, 3/4, F	
	Personals? <u>Yes/No</u> Glove/Center Box Access <u>Yes/No</u> Trunk Access? <u>Yes/No</u>	
	Keys? <u>Yes/No</u> How Many _____ How Many FOBS _____	
		☐ Ignition ☐ Transponder ☐ Push Button ☐ No Key ☐ FOB ☐ Keys ☐ Has Keys Does not Run or Start
VIN		<u>526716743</u>



Completed While

☐ Sunny ☐ Frost on Car ☐ Rainy/Wet
☐ Snow ☐ Ice Over ☐ Night

General Condition of Collateral

☐ Good ☐ Average ☐ Poor

M E C H A N I C A L	Engine	☒ OK	☐ Rough	☐ Burns Oil	
	Transmission	☒ OK	☐ Slips	☐ Leaks Oil	
	Clutch	☐ OK	☐ Fair	☐ Slips	
	Brakes	☒ OK	☐ Fair	☐ Pull Grab	
	Battery	☒ Yes ☐ No	☒ OK	☐ Dead ☐ Disc..	
Engine Intact:		☒ Yes ☐ No	This condition report was completed by a non mechanic and unit not road tested.		
T I R E S	L. Front	☒ Good	☐ Fair	☐ Poor	☐ None
	L. Rear	☐ Good	☐ Fair	☐ Poor	☐ None
	R. Front	☐ Good	☐ Fair	☐ Poor	☐ None
	R. Rear	☐ Good	☐ Fair	☐ Poor	☐ None
	Spare	☐ Good	☐ Fair	☐ Poor	☐ None
G L A S S	Windshield	☒ OK	☐ Crk	☐ Chip	☐ Missing
	L. Front	☐ Good	☐ Fair	☐ Poor	☐ None
	L. Rear	☐ Good	☐ Fair	☐ Poor	☐ None
	R. Front	☐ Good	☐ Fair	☐ Poor	☐ None
	R. Rear	☐ Good	☐ Fair	☐ Poor	☐ None
I N T E R	Inst Panel	☒ Good	☐ Fair	☐ Poor	☐ None
	F. Seats	☐ Good	☐ Fair	☐ Poor	☐ None
	R. Seats	☐ Good	☐ Fair	☐ Poor	☐ None
	Door Panels	☐ Good	☐ Fair	☐ Poor	☐ None
	Mat Carpet	☐ Good	☐ Fair	☐ Poor	☐ None
O R	Headliner	☐ Good	☐ Fair	☐ Poor	☐ None
	EQUIPMENT				
	☐ A/C ☐ Rear A/C ☐ Auto Trans ☐ 3rd Row ☐ Manual Trans ☐ Navigation ☐ Power Steering ☐ Backup Camera ☐ Power Brakes ☐ Heated Seats ☐ Power Windows ☐ Coated Seats ☐ Power Seats ☐ Power Door Locks ☐ Power Mirrors ☐ Cruise Control ☐ Tilt Wheel ☐ Sun Roof ☐ AM FM ☐ CD ☐ DVD ☐ Amp Subwoofer ☐ Touch Display ☐ Leather Seats ☐ EV Charger ☐ Breathalyzer ☐ Trailer Hitch ☐ Bed Liner ☐ Step Rails ☐ Tool Box Locked Yes / No ☐ Bed Cover or Cap Locked Yes / No ☐ Hubcaps If _____ ☐ Factory Rims ☐ Aftermarket Rims				

Completed By _____

Date _____

Comments Rust all over

Auction/Dealer Receipt for Repossession

Date _____ Time _____

The undersigned acknowledges receipt of the above described vehicle in identical condition listed above.

Printed Name _____

Signature _____

Witness _____