


Lot Space # _____ Summary Reference No 342020

Client <u>City of Chesapeake</u> Lien Holder		Vehicle Info	
Customer Name _____		Year <u>1988</u> Make <u>Bame</u> Color <u>White</u>	
Asset # <u>YT1014</u>		Model <u>Trailer</u> Doors _____ Ebrake: Yes / No	
Unit Secured From <u>956 Greenbrier Pkwy</u>		License No. _____ State _____ Exp. Date _____	
Date Recovered <u>10/23/25</u>		Mileage _____ ☐ Won't Display Lasso lock: Yes / No	
Time: <u>5:00</u> AM or PM		Heavy Damage: Yes / No Airbags Deployed: Yes / No	
Storage Address: Summs Ship and Collateral Solutions 2616 Quality Court Virginia Beach, VA 23454		P/U By _____ Tow By & Truck # _____ Tow from F or R _____ Used ☐ Go Jacks ☐ Dolly ☐ Roll Back ☐ None ☐ Shift Lock Customer Aware? <u>Yes/No</u> Able to Get Into Unit? <u>Yes/No</u> Insp _____ Vehicle Locked at Time of Repo? <u>Yes/No</u> Fuel: E, 1/4, 1/2, 3/4, F Personal? <u>Yes/No</u> Glove/Center Box Access <u>Yes/No</u> Trunk Access? <u>Yes/No</u> Keys? <u>Yes/No</u> How Many _____ How Many FOBS _____	
Release Hours By Appointment Only		K ☐ Ignition E ☐ Transponder V ☐ Push Button S ☐ No Key ☐ FOB ☐ Keys ☐ Has Keys Does not Run or Start	
VIN <u>1B905022X85026001</u>			



Completed While

☐ Sunny ☐ Frost on Car ☐ Rainy/Wet
☐ Snow ☐ Ice Over ☐ Night

General Condition of Collateral

☐ Good ☐ Average ☐ Poor

MECHANICAL	Engine	☐ OK	☐ Rough	☐ Burns Oil
	Transmission	☐ OK	☐ Slips	☐ Leaks Oil
	Clutch	☐ OK	☐ Fair	☐ Slips
	Brakes	☐ OK	☐ Fair	☐ Pull Grab
	Battery	☐ Yes ☐ No	☐ OK	☐ Dead ☐ Disc..
Engine Intact: ☐ Yes ☐ No This condition report was completed by a non mechanic and unit not road tested.				
TIRES	☒ Good	Fair	Poor	None
	L. Front			
	L. Rear			
	R. Front			
	R. Rear			
GLASS	☒ OK	Crk	Chip	Missing
	Windshield			
	L. Front			
	L. Rear			
	R. Front			
INTERIOR	☒ Good	Fair	Poor	None
	Inst Panel			
	F. Seats			
	R. Seats			
	Door Panels			
EQUIPMENT	☐ Jack	☐ Spare Wheel	☐ Duals	
	Windshield			
	L. Front			
	L. Rear			
	R. Front			
EQUIPMENT	☐ A/C	☐ Rear A/C		
	☐ Auto Trans	☐ 3rd Row		
	☐ Manual Trans	☐ Navigation		
	☐ Power Steering	☐ Backup Camera		
	☐ Power Brakes	☐ Heated Seats		
EQUIPMENT	☐ Power Windows	☐ Coated Seats		
	☐ Power Seats			
	☐ Power Door Locks			
	☐ Power Mirrors			
	☐ Cruise Control			
EQUIPMENT	☐ Tilt Wheel			
	☐ Sun Roof			
	☐ AM FM ☐ CD ☐ DVD			
	☐ Amp Subwoofer			
	☐ Touch Display			
EQUIPMENT	☐ Leather Seats			
	☐ EV Charger			
	☐ Breathalyzer			
	☐ Trailer Hitch			
	☐ Bed Liner			
EQUIPMENT	☐ Step Rails			
	☐ Tool Box Locked Yes / No			
	☐ Bed Cover or Cap Locked Yes / No			
	☐ Hubcaps # _____			
	☐ Factory Rims			
EQUIPMENT	☐ Aftermarket Rims			

Completed By _____

Date _____

Comments

Rusty, rotten wood boards

Auction/Dealer Receipt for Repossession

Date _____ Time _____

The undersigned acknowledges receipt of the above described vehicle in identical condition listed above.

Printed Name _____

Signature _____

Witness _____