

Trailer Condition Report:

Equipment Information:

Unit No: 00G306

Year: 2013

Make: BELSHE

Model: WB14

VIN/SN: 16JF01924D1047042

Miles/Hrs.:

Equipment Condition:

Mechanical Condition: Good - Some Parts May Require Repair or Replacement Soon

Interior Condition: Good - Some Parts May Require Repair or Replacement Soon

Exterior Condition: Good - Some Parts May Require Repair or Replacement Soon

Chassis:

GVWR: 14,000 lbs

Tire Size: LT235/85R16

Braking:

Comments: Tanndem Axel

Suspension:

Sliding Tandem Axle: Yes

Deck

Dimensions: **Length:** 19' **Width:** 6'9

Ramps (if equipped) Flip-Up

Specialized Equipment:

Type: **Details:**

Type: **Details:**

Notes: pindle hitch, tandle axel, wood floor is in good shape

Notes: