

Trailer Condition Report:

Equipment Information:

Unit No: 00G310

Year: 2014

Make: BELSHE

Model:

VIN/SN: 16JF01925E1047701

Miles/Hrs.:

Equipment Condition:

Mechanical Condition: Good - Some Parts May Require Repair or Replacement Soon

Interior Condition: Good - Some Parts May Require Repair or Replacement Soon

Exterior Condition: Good - Some Parts May Require Repair or Replacement Soon

Chassis:

GVWR: 7,000

Suspension:

Tire Size: LT235/85R16

Sliding Tandem Axle: Yes

Braking:

Comments: Tanndem Axel

Deck

Dimensions: Length: 19' Width: 6'9

Ramps (if equipped)

Specialized Equipment:

Type: Details:

Type: Details:

Notes: 19 ft long, 6 ft 9 in wid, wood deck in good shape, ramps, pindle hitch

Notes: