

Heavy Equipment Condition Report:

Asset Information:

Equipment Type: Excavator

Other: _____

Unit No: 00G502

Year: _____

Make: JOHN DEERE

Model: 27D

VIN/SN: 1FF027DXCDG258843

Miles/Hrs.: _____

Engine Information:

Year: 2014

Make: Yanmar

Model: 3TNV88

HP: 26

SN: _____

Fuel Type: Diesel

Asset Condition:

Mechanical Condition: Fair - Starts and operates but some parts require repair or replacement.

Interior Condition: Good - Damage is limited to normal wear and minor scratches.

Exterior Condition: Good - Minor dings and scratches

Hydraulics are Functional: Yes

Hydraulic Leaks Present: No

Unit Moves FWD/REV: Both

All Attachments Articulate: Yes

Notes: _____

Control Station Type: Canopy

AC/Heat: No

AC/Heat working: N/A

Additional Equipment: Bucket

Chassis:

Powertrain Type:

Propulsion Type: Track, Rubber

Track Condition: Fair - Track condition shows heavy use and may require maintenance

Wheel Condition: N/A

Tire Size:

Front:

Rear(s):

Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: _____

Type: _____

Details: _____

Type: _____

Details: _____

Additional Notes:

Aux hyd, canopy, tracks are fair