

Heavy Equipment Condition Report:

Asset Information:

Equipment Type: Backhoe

Other: _____

Unit No: 00G504

Year: _____

Make: JOHN DEERE

Model: 310K

VIN/SN: 1T0310KXJEE257352

Miles/Hrs.: N/A

Engine Information:

Year: 2014

Make: John Deere

Model: 4045HT054

HP: 70

SN: _____

Fuel Type: Diesel

Asset Condition:

Mechanical Condition: Very Good - Starts and operates with no known mechanical defects.

Interior Condition: Very Good - No visible signs of damage.

Exterior Condition: Good - Minor dings and scratches

Hydraulics are Functional: Yes

Hydraulic Leaks Present: No

Unit Moves FWD/REV: Both

All Attachments Articulate: Yes

Notes: _____

Control Station Type: Canopy

AC/Heat: No **AC/Heat working:** N/A

Additional Equipment: Bucket

Chassis:

Powertrain Type: 2WD

Propulsion Type: Wheel, Pneumatic - All Terrain

Track Condition:

Wheel Condition: Good - Wheel condition shows normal wear from use

Tire Size: **Front:**

Rear(s): 19.5L-24

Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: _____

Type: _____

Details: _____

Type: _____

Details: _____

Additional Notes:

QC, 2 wheel drive, bucket, low hour, great shape, paint peeling on hood, tear in seat, aux hyd