

Trailer Condition Report:

Equipment Information:

Unit No: 99279

Year: 2006

Make:

Model:

VIN/SN: TR193894

Miles/Hrs.:

Equipment Condition:

Mechanical Condition: Good - Some Parts May Require Repair or Replacement Soon

Interior Condition: Good - Some Parts May Require Repair or Replacement Soon

Exterior Condition: Good - Some Parts May Require Repair or Replacement Soon

Chassis:

GVWR: No Tag

Tire Size: ST235/85R16

Braking:

Comments:

Suspension:

Sliding Tandem Axle: Yes

Deck

Dimensions: Length: 12' Width: 6'5"

Ramps (if equipped)

Specialized Equipment:

Type: **Details:**

Type: **Details:**

Notes: Bed is in great shape

Notes: