

## CAT FACTS Report, Undercarriage Report and Work Order History

Engine serviced, with all interior and exterior air filters replaced, checked for leaks and topped off fluids as needed, Final drives drained, flushed, and refilled as needed, both right and left sprocket segments replaced, replaced both bottom belly pan actuator motors (to ensure proper operation), Installed a new belly pan actuator control box, Replaced and installed lights as needed, Inspected and tested the fire suppression system (operational), Replaced cab glass as needed, Replaced condenser fan, Replaced AC dryer and accumulator, Confirmed AC system is operational and blowing cold, Installed a new "Turbo II HD" precleaner bowl, checked hydraulic hoses and replaced as needed, installed new right and left door wiper motors as well as wiper blades, removed shims from left and right trunnion ball arms as needed, installed a new engine pressure sensor, installed new battery bracket tie downs and bolts, installed new engine air filter housing clips as needed, installed new exhaust clamps as needed, installed new hydraulic fan manifold, ran cat ET to make sure no active codes, oil samples available upon request, completed full cleaning, paint, and decals, Verified the following machine functions are operational: starts and runs, forward and reverse, implement functions, brakes, and parking brake.

### Additional details:

Full factory Waste Handler specifications, 8SU blade with trash rack, Trimble grade control, functioning fire suppression system, good undercarriage, Machine operated primarily in a mulch/compost environment (not trash), Ex-municipal machine, maintained by the local CAT dealer.

(All supporting information is included in the attached CAT FACTS)