

Vehicle Inspection Form

1242.9 hrs

Inventory ID:

Asset Number: 48

Fair Market Value: 2000

Short Description:

Year 2020 Make X-Mark Model 60" zero turn

VIN: 408928607 Title Restriction: ☐ Y ☐ N

Odometer: ☐ Miles ☐ Kilometers Odometer Accurate ☐ Y ☐ N:

Long Description:

This Vehicle: ☐ Starts ☐ Starts with a Boost & ☐ Runs/Driveable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only

Engine- Type: ☐ L, V ☐ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid

Engine Condition: ☐ Runs ☐ Needs repair ☐ is in unknown condition

Repairs needed:

This vehicle was maintained every ☐ Days ☐ Hours ☐ Miles

Date Removed From Service: Maintenance Records: ☐ Available ☐ Not Available For Inspection

Transmission: ☐ Automatic ☐ Manual ☐ Speed Condition: ☐ Operable ☐ Needs repair ☐ Is Unknown Condition

Repairs Needed:

Drivetrain: ☐ 2 Wheel Drive ☐ 4 Wheel Drive Condition:

Exterior: Color: Red Windows: ☐ No Cracked Glass ☐ Cracked

Minor: ☐ Dents ☒ Scratches ☒ Dings Tire Condition: Tread: #Flat Hubcaps #

Major Damage to: ~~Scratches~~

Additional Damage:

Decals: ☐ None ☐ Have Been Sprayed or ☐ Have been Removed & ☐ Impressions Remain ☐ No Impressions

Emergency equip: ☐ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes

Interior: Color ☐ Cloth ☐ Vinyl ☐ Leather

Damage to Seats:

Damage to Dash/Floor:

Radio: ☐ Stock or ☐ Brand & Model: ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD

☐ AC (Condition: ☐ Cold ☐ Unknown) ☐ No AC Air Bags: ☐ Driver's Side ☐ Dual

☐ Cruise Control ☐ Tilt Steering ☐ Remote Mirrors ☐ Climate Control

Power: ☐ Steering ☐ Windows ☐ Door Locks ☐ Seats

Additional Equipment:

Manufacturer Model Serial #

☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand ☐ Hitch: Type

Location of Asset: Parks Facility at baseball park

For more information contact:

Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.