Boom Truck Condition Report:

Equipment Information:										
Unit No:	FT5531			_	Er	ngine Info	ormation:			
Year:	2011			Year:	2011					
Make:	FREIGHTLINER			Make:	e: CUMMINS			HP	HP:	
Model:	M2 106			Model:	ISC					
VIN/SN:	1FVHCYBS6BDA	V1531		SN:						
Miles/Hrs.:	295873 / 10361			Fuel Type:	Diesel					
Equipment Condition:										
Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.								oon.		
Interior Condition: Good - Damage is limited to normal wear and minor scratches.										
Exterior Condition: Good - Minor dings and scratches										
AC/H	eat Functional:	Yes								
	Leaks Present:	Not Seen Engine Displacement:						nders	6	
Sleeper (if Applicable):		Length:		_# of Bunks:		Aux	x Power Unit? No		No	
Additio	nal Equipment:									
Transmission:										
	smission Make: EATON FULLER									
	Auto / Manual: Automatic				Number of Speeds:					
Truck Moves FWD/REV: Both										
	Comments:									
	-									
Chassis:										
Frame Rails: Double			Notes:							
					Notes:					
	Wheel Base:			in.						
Axle Weigh	t Ratings (LBS):	GVWR:	54,600	- Front Axel:	14,600		Rear(s):	40,000		
0	Tire Size:	Front:	315/80/	-		Rear(s):	11R22.5			
	Comments:	·								
	-									
Flatbed										
E	Bed Dimensions:	Length:	24' 6"	ft.	Width:	8	ft.			
Conveyor/Boom Make:				Co	nveyor/Boo	m Model:	_			
Cor	veyor/Boom Is F	unctional:								
Additio	nal Notes:									