## **Fork Lift Condition Report:**

			FORK	litt intorma	ltion		
Unit No:	FK9232				<b>Engine Information:</b>		
Year:	2005			Year:			
Make:	Nissan			Make:	Nissan		
Model:	MPL02A25LV			Model:	5NSXB02.147C <b>HF</b>	<b>)</b> :	55
VIN/SN:	PL02-9H1232			SN:			
Miles/Hrs.:				Fuel Type:	Liquid Propane		
Forklift Condition							
Mech	anical Condition:	Fair - Sta	arts and ope	rates but som	e parts require repair or replacement.		_
In	terior Condition:	Fair - Int	erior is heav	vily worn.			
Exterior Condition: Fair - Visible dents and scratches							
Control Station:							
Steering Control Operationa			Yes		Notes:		
	<b>Control Statio</b>	n Type:	Canopy				
Δ	C/Heat (If enclose	ed Cab):	No		AC/Heat Functional:		
	Additional Equ	ipment:					
Hydraulics:							
Hydraulio	draulics are Functional: Yes Hydraulic Leaks Present: No						
-	Moves FWD/REV:	Both		iiyaic	idite Ecurs i reseite.		
	hments Articulate Yes			Notes:			
			ter renorted	-	rect, hours unknown, many waning lights		
Undercarriage:							
Po	wertrain Type:2WD			Drivetrain is functional:			
Tire Type: Solid Pneur			eumatic	matic Non-Marking?			
	Comments:						
				Mast:			
	Mast Type:	3-Stage					
N	/lax Lift Height:	187In.		Lowered Mast Height:I			۱.
	Fork Length:	48	_In.				
i	Fork Positioner:	No	Notes:				
	Side Shift:	Yes	Notes:				
	Scales:	No	Notes:				
Othe	er Attachments:	No	Notes:				