

Boom Truck Condition Report:

Equipment Information:

Unit No: WB99571 **Engine Information:**
Year: 2007 **Year:** _____
Make: Sterling **Make:** Cat **HP:** _____
Model: 2FZSAZDE27AY21571 **Model:** C13
VIN/SN: #REF! **SN:** _____
Miles/Hrs.: 269068/10611 **Fuel Type:** Diesel

Equipment Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.
Interior Condition: Fair - Interior is heavily worn.
Exterior Condition: Fair - Visible dents and scratches
AC/Heat Functional: Yes
Leaks Present: Not Seen **Engine Displacement:** 12.5 **Number of Cylinders:** 6
Sleeper (if Applicable): **Length:** _____ **# of Bunks:** _____ **Aux Power Unit?** _____
Additional Equipment: _____

Transmission:

Transmission Make: _____
Auto / Manual: Automatic **Number of Speeds:** _____
Truck Moves FWD/REV: Both
Comments: _____

Chassis:

Frame Rails: Double **Notes:** _____
Suspension: Air **Notes:** _____
Wheel Base: _____ **in.** _____
Axle Weight Ratings (LBS): **GVWR:** 68,000 **Front Axel:** 18,000 **Rear(s):** 40,000
Tire Size: **Front:** 65R22.5 **Rear(s):** 70R22.5
Comments: _____

Flatbed

Bed Dimensions: **Length:** _____ **ft.** **Width:** _____ **ft.**
Conveyor/Boom Make: HIAB **Conveyor/Boom Model:** _____
Conveyor/Boom Is Functional: _____

Additional Notes:

Wallboard