## **Boom Truck Condition Report:**

			Equip	oment infor	mation:				
Unit No:	BT5396			_	Engine Information:				
Year:	2016			Year:	2016				
Make:	Freightliner			Make:	Cummins			HP:	345
Model:	108SD			Model:					
VIN/SN:	1FVHG5CY9GH	HB4396		SN:	73838483				
Miles/Hrs.:	122629			Fuel Type:	Diesel				
Equipment Condition:									
Mechan	ical Condition:	Poor - Wil	l not start	or operate an	d is in need	of repair.			
Inte	rior Condition:	Good - Da	mage is li	mited to norm	al wear and	minor scra	tches.		
Exte	rior Condition:	Good - Mi	nor dings	and scratches					
AC/H	eat Functional:	Yes							
	<b>Leaks Present:</b>	Not Seen Engine Displacement: Number of Cylinders					(	6	
Sleeper	(if Applicable):	Length: # of Bunks: Aux Power Un				Power Unit?			
Additio	nal Equipment:								
				Transmissi	on:				
Trans	mission Make:	Allison							
	Auto / Manual:	Automatic Number of Speeds: 6							
Truck Mo	oves FWD/REV:	Unknown							
	Comments:								
Chassis:									
	Frame Rails:								
						-			
	Suspension: Wheel Base:			in.		Notes:			
Aylo Woigh			64.000	_'''. Front Axel:	19.000		Poor(s): 22.0	00	
Axie weigh	t Ratings (LBS): Tire Size:	_	64,000	_	18,000	Poor(s):	Rear(s): 23,0	00	
	Comments:	Front: _	315/80/	22.5		Rear(s):	11r22.5		
	comments:								
				Flatbed					
	Bed Dimensions:	Length:	20	ft.	Width:	0	ft.		
	or/Boom Make:	_	20	_	_		F200BS.23		
-	nveyor/Boom Is I		Could no	_ ot confirm	iveyor, boo	iii ivioaci.	120003.23		
30.	3, 21, 200 io	_							
- ۲ داله له ۸	and Nate	Battery dea	d, we atte	empted to jum	p but it was	to dead. Th	ne location had no	ot starte	ed the
Additio	nal Notes:	unit in 2 weeks and could not jump the unit for us.							