

Vehicle Condition Report:

Vehicle Information:

Vehicle Type: Truck

Other: _____

Unit No: PK20620

Engine Information:

Year: 2020

Year: 2020

Make: Chevrolet

Make: GM

Model: Colorado

Model: V6 VVT

VIN/SN: 1GCGTCEN5L1235620

SN: _____

Miles: 116172

Fuel Type: Gasoline

Vehicle Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Good - Damage is limited to normal wear and minor scratches.

Exterior Condition: Fair - Visible dents and scratches

Condition Comments: _____

Engine Displacement: 3.6 Liters. Crankshaft (V, Inline, Boxer) _____ Cylinders: 6

Power Windows: Yes

Power Locks: Yes

Air Conditioner / Heat: Yes

AC / Heat Functional: Yes

Transmission: Automatic

Number of Manual Speeds: _____

Unit Moves FWD/REV: Both

Four Wheel Drive (4x4): Yes

Functional: _____

Additional Equipment: _____

Chassis:

Suspension: Spring

Notes: _____

Wheelbase: _____

GVWR: 6000

Front: 3200

Rear(s): 3500

Tire Size: _____

Front: 265/60R18

Rear: 265/60R18

Comments: _____

Cargo / Passenger Vans

Passenger Van Seating: _____ Rows _____

Cargo Van Box Dimensions:

Length: _____

Width: _____

Height: _____

Additional Notes: _____