

Boom Truck Condition Report:

Equipment Information:

Unit No: BT17010
Year: 2017
Make: Freightliner
Model: 108SD
VIN/SN: 1FVHG5CY5HHJH7010

Miles/Hrs.: 124102

Engine Information:
Year: _____
Make: Cummins
Model: ISL
SN: 74068730

Fuel Type: Diesel

Starts and Runs: Yes

HP: _____

Equipment Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Good - Minor dings and scratches

AC/Heat Functional: Yes

Leaks Present: Not Seen Engine Displacement: 8.9 Number of Cylinders 6

Air Lift 3rd Axle in front of drive wheels _____ Air Lift Tag Axle behind drive wheels _____

Carrier Type: Flatbed Truck

Transmission:

Transmission Make: Allison

Auto / Manual: Automatic Number of Speeds: _____

Truck Moves FWD/REV: Both

Comments: _____

Chassis:

Frame Rails: Double Notes: _____

Suspension: Air Notes: _____

Wheel Base: 264 in. _____

Axle Weight Ratings (LBS): GVWR: 64,000 Front Axle: 18,000 Rear(s): 46,000

Tire Size: Front: 315/80R22.5 Rear(s): 11R22.5

Comments: _____

Flatbed

Bed Dimensions: Length: 25 Ft. Width: 8 Ft.

Lifting Equipment Type: Wallboard Crane Other: _____

Conveyor/Boom Is Functional: Could not confirm

Turntable Make: HIAB Turntable Model: 166 DL-3HIPRO

Conveyor/Boom Make: HIAB Conveyor/Boom Model: XS 166L

Additional Equipment: _____