Boom Truck Condition Report:

			Lquip		mation.				
Unit No:	CO10344			Engine Information:					
Year:	2015			Year:					
Make:	Freightliner			Make:	Cummins			HP:	
Model:	108DC			Model:					
VIN/SN:	3ALHG5CY8FDG	SL9344		SN:					
Miles/Hrs.:	226964			Fuel Type:	Diesel				
Equipment Condition:									
Mechanical Condition:		Good - Starts and operates; Some parts may require repair or replacement soon.							
Interior Condition:		Good - Damage is limited to normal wear and minor scratches.							
Exterior Condition:		Fair - Visib	le dents a	nd scratches					
AC/H	eat Functional:								
	Leaks Present:	Not Seen	ngine Di	splacement:	8.9	Numb	er of Cylin	ders	6
Sleeper (if Applicable):		Length: # of Bunks:			Aux Power Uni			it?	
Additio	nal Equipment:	_		·					
	- -								
				Transmissio	n:				
Transmission Make:		Allison							
Auto / Manual:		Automatic Nun				Number o	f Speeds:		
Truck Moves FWD/REV:		Both			-		·-		
	Comments:								
Chassis:									
	Frame Rails:	Double				Notes:			
	Suspension:	Air			_	Notes:			
	Wheel Base:			in.					
Axle Weigh	t Ratings (LBS):	GVWR:_	60,000	Front Axel:	20,000		Rear(s):	40,000	
	Tire Size:	Front:	425/65R	22.5		Rear(s):	11R22.5		
	Comments:								
				Flatbed					
	Bed Dimensions:	Length:	25 ft. Width: 8 ft.						
Conveyor/Boom Make:			.,	Cor	nveyor/Boo	om Model: _	FBR-6-40		
Cor	nveyor/Boom Is F	-unctional: _	Yes						
Additio	onal Notes:								