

Boom Truck Condition Report:

Equipment Information:

Unit No: CO10375

Year: 2016

Make: Freightliner

Model: 108SD

VIN/SN: 1FVMG5CY7GHGX9375

Miles/Hrs.: _____

Engine Information:

Year: 2016

Make: Cummins

Model: ISL

SN: _____

HP: 350

Fuel Type: Diesel

Equipment Condition:

Mechanical Condition: Poor - Will not start or operate and is in need of repair.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

AC/Heat Functional: _____

Leaks Present: _____

Engine Displacement: 8.9

Number of Cylinders 6

Sleeper (if Applicable): Length: _____

of Bunks: _____

Aux Power Unit? _____

Additional Equipment: _____

Transmission:

Transmission Make: Allison

Auto / Manual: Automatic

Number of Speeds: _____

Truck Moves FWD/REV: Unknown

Comments: _____

unit has been sitting, seller states it is a non-runner

Chassis:

Frame Rails: _____

Notes: _____

Suspension: Spring

Notes: _____

Wheel Base: _____ in.

Axle Weight Ratings (LBS): GVWR: 68,000 Front Axel: 20,000 Rear(s): 33,200

Tire Size: Front: 425/65R22.5

Rear(s): 11R22.5

Comments: _____

Flatbed

Bed Dimensions: Length: 26' ft.

Width: 102" ft.

Conveyor/Boom Make: Cleasby

Conveyor/Boom Model: FBR-6-40

Conveyor/Boom Is Functional: Could not confirm

Additional Notes: _____