

Boom Truck Condition Report:

Equipment Information:

Unit No: CO17090
Year: 2017
Make: Freightliner
Model: M2 106
VIN/SN: 3ALHCYCYXHDJF2090

Miles/Hrs.: 210472

Engine Information: Starts and Runs: Yes
Year: 2017
Make: Cummins
Model: ISL
SN: _____

Fuel Type: Diesel

Equipment Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

AC/Heat Functional: Yes

Leaks Present: Not Seen Engine Displacement: 8.9 Number of Cylinders 6
Air Lift 3rd Axle in front of drive wheels No Air Lift Tag Axle behind drive wheels No

Additional Equipment: Flatbed Truck

Transmission:

Transmission Make: Allison
Auto / Manual: Automatic Number of Speeds: _____
Truck Moves FWD/REV: Both
Comments: _____

Chassis:

Frame Rails: Double Notes: _____
Suspension: Air Notes: _____
Wheel Base: in. _____
Axe Weight Ratings (LBS): GVWR: 56,000 Front Axle: _____ Rear(s): _____
Tire Size: Front: 385/65R22.5 Rear(s): 11R22.5
Comments: _____

Flatbed

Lifting Equipment Type: Conveyor Other: _____
Conveyor/Boom Is Functional: Yes
Turntable Make: _____ Turntable Model: _____
Conveyor/Boom Make: Cleasby Conveyor/Boom Model: FBR-6-40