Boom Truck Condition Report:

Equipment Information:									
Unit No:	CO6152			Engine Information:					
Year:	2015			Year:	2015				
Make:	Freightliner			Make: Cummins			HP:		
Model:	M2106			Model:	ISL				
VIN/SN:	3ALHCYCY9FDG	D9152		SN:					
Miles/Hrs.:	151766			Fuel Type:	Diesel				
Equipment Condition:									
Mechanical Condition:		Good - St	arts and o	perates; Some	parts may	require repa	air or replace	ment so	on.
Interior Condition:				imited to norm					
Exterior Condition:		Good - M	inor dings	and scratches					
AC/Heat Functional:		Yes							
Leaks Present:		Not Seen	Engine D	isplacement:	8.9	Numb	er of Cylind	lers	6
Sleeper (if Applicable):		Length:		# of Bunks:		Aux	Power Unit	:?	
Additio	nal Equipment:								
Transmission:									
Trans	smission Make:								
Auto / Manual:		Automatic Number of Speeds:							
Truck Moves FWD/REV:		Both							
Comments:									
Chassis:									
	Frame Rails:	Double		CHassis.		Notes:			
	Suspension:					- Notes: - Notes:			
	Wheel Base:	Ayn		in.		Notes.			
Avle Weigh	t Ratings (LBS):	GVWR:	56,000	_'''· Front Axel:	16,000		Rear(s):	40,000	
Axic Weigh	Tire Size:	Front:	385/65F		10,000	Rear(s):	11R22.5	40,000	
	Comments:	110116.	303/031	(22.5		_ '\car\3)	111122.5		
	Comments								
Flatbed									
	Bed Dimensions: Length: 23'10" f								
Conveyor/Boom Make:									
-	nveyor/Boom Is F		Yes	- 		_			
		•							
Additio	onal Notes:								