

Boom Truck Condition Report:

Equipment Information:

Unit No: CO9172
Year: 2014
Make: Freightliner
Model: M2 106
VIN/SN: 3ALHCYCYXEDFT8172

Miles/Hrs.: 237726

Engine Information:

Year: 2014
Make: Cummins
Model: ISL
SN:

Fuel Type: Diesel

Equipment Condition:

Mechanical Condition: Fair - Starts and operates but some parts require repair or replacement.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

AC/Heat Functional:

Leaks Present: Not Seen Engine Displacement: 8.9 Number of Cylinders 6

Sleeper (if Applicable): Length: # of Bunks: Aux Power Unit?

Additional Equipment:

Transmission:

Transmission Make: Allison

Auto / Manual: Automatic Number of Speeds:

Truck Moves FWD/REV: Unknown

Comments:

Chassis:

Frame Rails: Notes:

Suspension: Spring Notes:

Wheel Base: in.

Axle Weight Ratings (LBS): GVWR: 56,000 Front Axle: Rear(s):

Tire Size: Front: 385/65R22 Rear(s): 385/65R22

Comments: Tires minor dry rot

Flatbed

Bed Dimensions: Length: 45' ft. Width: 102" ft.

Conveyor/Boom Make: Cleasby Conveyor/Boom Model: RTH-3000

Conveyor/Boom Is Functional: Could not confirm

Additional Notes: