

Boom Truck Condition Report:

Equipment Information:

Unit No: CO9297
Year: 2007
Make: Freightliner
Model: M2106
VIN/SN: 1FVHCYDJ57DY32971
Miles/Hrs.: 223612

Engine Information:
Year: 2007
Make: Mercedes Benz
Model: MBE-900
SN: _____
Fuel Type: Diesel

Equipment Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

AC/Heat Functional: Yes

Leaks Present: Not Seen Engine Displacement: 7.2 Number of Cylinders 6
Sleeper (if Applicable): Length: _____ # of Bunks: _____ Aux Power Unit? _____

Additional Equipment: _____

Transmission:

Transmission Make: Eaton Fuller
Auto / Manual: Manual Number of Speeds: 8
Truck Moves FWD/REV: Both
Comments: _____

Chassis:

Frame Rails: _____ Notes: _____
Suspension: Spring Notes: _____
Wheel Base: _____ in. _____
Axe Weight Ratings (LBS): GVWR: 56,000 Front Axel: 16,000 Rear(s): 40,000
Tire Size: Front: 385/65R22.5 Rear(s): 11R22.5
Comments: _____

Flatbed

Bed Dimensions: Length: 26 ft. Width: 94" ft.
Conveyor/Boom Make: Cleasby Conveyor/Boom Model: FBR-6-40
Conveyor/Boom Is Functional: Yes

Additional Notes: