

# Boom Truck Condition Report:

## Equipment Information:

Unit No: CO9428

### Engine Information:

Year: 2005

Year: 2005

Make: Sterling

Make: CAT

HP: \_\_\_\_\_

Model: Acterra

Model: C7

VIN/SN: 2FZACGDCX5AU88428

SN: \_\_\_\_\_

Miles/Hrs.: 150300

Fuel Type: Diesel

## Equipment Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

AC/Heat Functional: Yes

Leaks Present: Not Seen Engine Displacement: 7.2 Number of Cylinders 6

Sleeper (if Applicable): Length: \_\_\_\_\_ # of Bunks: \_\_\_\_\_ Aux Power Unit? \_\_\_\_\_

Additional Equipment: \_\_\_\_\_

## Transmission:

Transmission Make: \_\_\_\_\_

Auto / Manual: Manual Number of Speeds: 6

Truck Moves FWD/REV: Both

Comments: \_\_\_\_\_

## Chassis:

Frame Rails: \_\_\_\_\_ Notes: \_\_\_\_\_

Suspension: Spring Notes: \_\_\_\_\_

Wheel Base: \_\_\_\_\_ in. \_\_\_\_\_

Axle Weight Ratings (LBS): GVWR: 33,000 Front Axle: 12,000 Rear(s): 21,000

Tire Size: Front: 11R22.5 Rear(s): 11R22.5

Comments: \_\_\_\_\_

## Flatbed

Bed Dimensions: Length: 20 ft. Width: 102" ft.

Conveyor/Boom Make: Cleasby Conveyor/Boom Model: FBR-6-31

Conveyor/Boom Is Functional: Yes

Additional Notes: