

# Boom Truck Condition Report:

## Equipment Information:

Unit No: CO9966  
Year: 2013  
Make: Peterbilt  
Model: 337  
VIN/SN: 2NP2HM7X0DM195966

Miles/Hrs.: 182365/10548

## Engine Information:

Year: 2013  
Make: PACCAR  
Model: PX-6  
SN:

Fuel Type: Diesel

## Equipment Condition:

**Mechanical Condition:** Good - Starts and operates; Some parts may require repair or replacement soon.

**Interior Condition:** Good - Damage is limited to normal wear and minor scratches.

**Exterior Condition:** Good - Minor dings and scratches

**AC/Heat Functional:** Yes

**Leaks Present:** Oil **Engine Displacement:** 9.3 **Number of Cylinders:** 8

**Sleeper (if Applicable):** Length: # of Bunks: **Aux Power Unit?**

**Additional Equipment:**

## Transmission:

**Transmission Make:** Allison

**Auto / Manual:** Automatic **Number of Speeds:**

**Truck Moves FWD/REV:** Both

**Comments:**

## Chassis:

**Frame Rails:** Single **Notes:**

**Suspension:** Air **Notes:**

**Wheel Base:** 190 in.

**Axle Weight Ratings (LBS):** GVWR: 33,000 **Front Axle:** 12,000 **Rear(s):** 21,000

**Tire Size:** Front: 11R22.5 **Rear(s):** 11R22.5

**Comments:**

## Flatbed

**Bed Dimensions:** Length: 24 ft. **Width:** 8.5 ft.

**Conveyor/Boom Make:** Cleasby **Conveyor/Boom Model:** FBR-6-36

**Conveyor/Boom Is Functional:** No

**Additional Notes:**

Boom moves up and down, has hydraulic pressure issue, Conveyor does not turn.  
See attached video