

Boom Truck Condition Report:

Equipment Information:

Unit No: CO99842

Year: 2017

Make: Freightliner

Model: 114SD

VIN/SN: 1FVHG3DV8HHHY0842

Miles/Hrs.: 192235

Engine Information:

Year: 2017

Make: Detroit

Model: DD13

SN: 471928S0408396

HP: _____

Fuel Type: Diesel

Equipment Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Good - Minor dings and scratches

AC/Heat Functional: Yes

Leaks Present: Not Seen

Engine Displacement: 12.8

Number of Cylinders

6

Sleeper (if Applicable): Length: _____

of Bunks: _____

Aux Power Unit? _____

Additional Equipment: _____

Transmission:

Transmission Make: Allison

Auto / Manual: Automatic

Number of Speeds: _____

Truck Moves FWD/REV: Both

Comments: _____

Chassis:

Frame Rails: Double

Notes: _____

Suspension: Spring

Notes: _____

Wheel Base: 260 in.

Axle Weight Ratings (LBS): GVWR: 59,840 Front Axel: 19,840 Rear(s): 40,000

Tire Size: Front: 385/65R22.5

Rear(s): 11R22.5

Comments: _____

Flatbed

Bed Dimensions: Length: 24'8" ft.

Width: 8'6" ft.

Conveyor/Boom Make: Cleasby

Conveyor/Boom Model: FBR 640

Conveyor/Boom Is Functional: Yes

Additional Notes: _____