

Boom Truck Condition Report:

Equipment Information:

Unit No: CO9148
Year: 2015
Make: Freightliner
Model: M2 106
VIN/SN: 3ALHCYCY7FDGD9148

Miles/Hrs.: 224064/6197

Engine Information:

Year: 2015
Make: Cummins
Model: ISL
SN: _____
Fuel Type: Diesel

Equipment Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

AC/Heat Functional: _____

Leaks Present: Not Seen **Engine Displacement:** 8.9 **Number of Cylinders:** 6

Sleeper (if Applicable): Length: _____ # of Bunks: _____ **Aux Power Unit?** _____

Additional Equipment: _____

Transmission:

Transmission Make: Allison

Auto / Manual: Automatic **Number of Speeds:** _____

Truck Moves FWD/REV: Unknown

Comments: _____

Chassis:

Frame Rails: _____ **Notes:** _____

Suspension: Spring **Notes:** _____

Wheel Base: _____ in. _____

Axle Weight Ratings (LBS): **GVWR:** 56,000 **Front Axel:** _____ **Rear(s):** _____

Tire Size: **Front:** _____ **Rear(s):** _____

Comments: Tires minor dry rot

Flatbed

Bed Dimensions: **Length:** 26' **ft.** **Width:** 8' **ft.**

Conveyor/Boom Make: Cleasby **Conveyor/Boom Model:** RTH-3000

Conveyor/Boom Is Functional: Yes _____

Additional Notes:

Starts and runs. Boom not tested stated in working condition.