

Heavy Equipment Condition Report:

Asset Information:

Equipment Type: Telehandlers

Other: _____

Unit No: FM03046

Year: 2003

Make: Gradall

Model: 534C-6

VIN/SN: 388046

Miles/Hrs.: 4801

Engine Information:

Year: _____

Make: Cummins

Model: 4B

HP: _____

SN: _____

Fuel Type: Diesel

Asset Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Good - Damage is limited to normal wear and minor scratches.

Exterior Condition: Good - Minor dings and scratches

Hydraulics are Functional: Yes

Hydraulic Leaks Present: Yes

Unit Moves FWD/REV: Both

All Attachments Articulate: Yes

Notes: frok tilt ram leak, undercarage

Control Station Type: Canopy

AC/Heat: _____ AC/Heat working: _____

Additional Equipment: _____

Chassis:

Powertrain Type: 4WD

Propulsion Type: Wheel, Pneumatic - All Terrain

Track Condition: _____

Wheel Condition: Good - Wheel condition shows normal wear from use

Tire Size: _____

Front: 13-24

Rear(s): 13-24

Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: 48forks and load backrest

Type: _____

Details: _____

Type: _____

Details: _____

Additional Notes:

two wheel steering