

Truck Tractor Condition Report:

Equipment Information:

Unit No:	FT4376	Engine Information:	
Year:	2016	Year:	
Make:	Freightliner	Make:	Cummins
Model:	108SD	Model:	ISL
VIN/SN:	1FVMG5CY9GHGX9376	HP:	310
KM/Hrs.:	162946	Fuel Type:	Diesel

Equipment Condition:

Mechanical Condition:	Fair - Starts and operates but some parts require repair or replacement.		
Interior Condition:	Fair - Interior is heavily worn.		
Exterior Condition:	Good - Minor dings and scratches		
AC/Heat Functional:	Yes		
Leaks Present:	Not Seen	Engine Displacement:	8.9
Sleeper (if Applicable):	Length:	Number of Cylinders	6
	# of Bunks:	Aux Power Unit?	
Additional Equipment:			

Transmission:

Transmission Make:			
Auto / Manual:	Automatic	Number of Speeds:	
Truck Moves FWD/REV:	Neither		
Comments:	Hole in radiator, brake chamber fell off- Will start but has issues running		

Chassis:

Frame Rails:	Double	Notes:				
Suspension:	Spring	Notes:				
Wheel Base:		in.				
Axle Weight Ratings (LBS):	GVWR:	68,000	Front Axel:	20,000	Rear(s):	13,200
	Tire Size:	Front:	425/65/R22.5	Rear(s):	11R22.5	
Comments:						

Specialized Equipment:

Type:		Details:	
Type:		Details:	
Notes:			
Notes:			