

Boom Truck Condition Report:

Equipment Information:

Unit No: FT9264
Year: 2013
Make: Freightliner
Model: 108SD
VIN/SN: 1FVHG5BS7DHBU0264

Miles/Hrs.: 217566

Engine Information:
Year: 2013
Make: Cummins
Model: ISC
SN: _____
Fuel Type: Diesel

Equipment Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

AC/Heat Functional: Yes

Leaks Present: Not Seen Engine Displacement: 8.3 Number of Cylinders 6

Sleeper (if Applicable): Length: _____ # of Bunks: _____ Aux Power Unit? _____

Additional Equipment: _____

Transmission:

Transmission Make: EATON FULLER

Auto / Manual: Manual Number of Speeds: 10

Truck Moves FWD/REV: Both

Comments: _____

Chassis:

Frame Rails: _____ Notes: _____

Suspension: Spring Notes: _____

Wheel Base: _____ in. _____

Axle Weight Ratings (LBS): GVWR: _____ Front Axle: _____ Rear(s): _____

Tire Size: Front: 11R22.5 Rear(s): 11R22.5

Comments: _____

Flatbed

Bed Dimensions: Length: 23'7" ft. Width: 8 ft.

Conveyor/Boom Make: _____ Conveyor/Boom Model: _____

Conveyor/Boom Is Functional: _____

Additional Notes: