

# Truck Tractor Condition Report:

## Equipment Information:

<b>Unit No:</b> FT99613	<b>Engine Information:</b>
<b>Year:</b> 2004	<b>Year:</b> 2004
<b>Make:</b> GMC	<b>Make:</b> Duramax
<b>Model:</b> C5500	<b>Model:</b> 6.6 L <b>HP:</b>
<b>VIN/SN:</b> 1GDE5C1264F512613	<b>SN:</b>
<b>KM/Hrs.:</b> 221649	<b>Fuel Type:</b> Diesel

## Equipment Condition:

**Mechanical Condition:** Good - Starts and operates; Some parts may require repair or replacement soon.

**Interior Condition:** Fair - Interior is heavily worn.

**Exterior Condition:** Fair - Visible dents and scratches

**AC/Heat Functional:** \_\_\_\_\_

**Leaks Present:** Not Seen **Engine Displacement:** 6.6 **Number of Cylinders:** 8

**Sleeper (if Applicable):** **Length:** \_\_\_\_\_ **# of Bunks:** \_\_\_\_\_ **Aux Power Unit?** \_\_\_\_\_

**Additional Equipment:** \_\_\_\_\_

## Transmission:

**Transmission Make:** \_\_\_\_\_

**Auto / Manual:** Automatic **Number of Speeds:** \_\_\_\_\_

**Truck Moves FWD/REV:** Both

**Comments:** \_\_\_\_\_

## Chassis:

**Frame Rails:** \_\_\_\_\_ **Notes:** \_\_\_\_\_

**Suspension:** Spring **Notes:** \_\_\_\_\_

**Wheel Base:** \_\_\_\_\_ in.

**Axle Weight Ratings (LBS):** **GVWR:** 19,500 **Front Axel:** 7,000 **Rear(s):** 13,500

**Tire Size:** **Front:** 225/70R19.5 **Rear(s):** 225/70R19.5

**Comments:** \_\_\_\_\_

## Specialized Equipment:

**Type:** \_\_\_\_\_ **Details:** \_\_\_\_\_

**Type:** \_\_\_\_\_ **Details:** \_\_\_\_\_

**Notes:** Deck Dimensions: 16Ft x 7Ft

**Notes:** \_\_\_\_\_