

Vehicle Condition Report:

Vehicle Information:

Vehicle Type: Box Truck

Other: _____

Unit No: ST9000

Engine Information:

Year: 2007

Year: 2007

Make: Freightliner

Make: Mercedes Benz

Model: M2 106

Model: MBE-900

VIN/SN: 1FVACWCS67DY33000

SN: _____

Miles: 153559

Fuel Type: Diesel

Vehicle Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

Condition Comments: _____

Engine Displacement: 6.4 **Liters. Crankshaft (V, Inline, Boxer)** _____ **Cylinders:** 6

Power Windows: Yes

Power Locks: Yes

Air Conditioner / Heat: Yes

AC / Heat Functional: Yes

Transmission: Manual

Number of Manual Speeds: 6

Unit Moves FWD/REV: Both

Four Wheel Drive (4x4): No

Functional: _____

Additional Equipment: _____

Chassis:

Suspension: Spring

Notes: _____

Wheelbase: _____

GVWR: 25500

Front: 8000

Rear(s): 17500

Tire Size: _____

Front: 295/75R22.5

Rear: 295/75R22.5

Comments: _____

Cargo / Passenger Vans

Passenger Van Seating: _____ **Rows:** _____

Cargo Van Box Dimensions: _____ **Length:** 28.5' **Width:** 8' **Height:** _____

Additional Notes: _____