

Truck Tractor Condition Report:

Equipment Information:

Unit No: TA17054
Year: 2017
Make: Freightliner
Model: Cascadia 113
VIN/SN: 3AKJGBDV0HSJH7054
KM/Hrs.: 358232

Engine Information:
Year: _____
Make: Detroit Diesel
Model: DD13
SN: _____
Fuel Type: Diesel

Equipment Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Good - Damage is limited to normal wear and minor scratches.

Exterior Condition: Good - Minor dings and scratches

AC/Heat Functional: Yes

Leaks Present: Not Seen Engine Displacement: 12.8 Number of Cylinders 6
Sleeper (if Applicable): Length: _____ # of Bunks: _____ Aux Power Unit? _____

Additional Equipment: _____

Transmission:

Transmission Make: Eaton Fuller
Auto / Manual: Automatic Number of Speeds: _____
Truck Moves FWD/REV: Both
Comments: _____

Chassis:

Frame Rails: Single Notes: _____
Suspension: Air Notes: _____
Wheel Base: in. _____
Axe Weight Ratings (LBS): GVWR: 52,000 Front Axel: 12,000 Rear(s): 40,000
Tire Size: Front: 295/75R22.5 Rear(s): 295/75R22.5
Comments: _____

Specialized Equipment:

Type: _____ Details: _____
Type: _____ Details: _____
Notes: _____
Notes: _____