

Truck Tractor Condition Report:

Equipment Information:

Unit No: TA19021
Year: 2019
Make: Freightliner
Model: Cascadia Axle: Tandem
VIN/SN: 1FUJGBDV5KLKE3021
KM/Hrs.: 225850/7871

Engine Information: Starts and Runs: Yes
Year: _____
Make: Detroit
Model: DD13 HP: _____
SN: 4.71929E+13
Fuel Type: Diesel

Equipment Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Good - Damage is limited to normal wear and minor scratches.

Exterior Condition: Good - Minor dings and scratches

AC/Heat Functional: Yes

Leaks Present: Not Seen Engine Displacement: 12.8 Number of Cylinders: 6

Sleeper (if Applicable): Length: _____ # of Bunks: _____ Aux Power Unit? _____

Additional Equipment: _____

Transmission:

Transmission Make: Eaton

Auto / Manual: Automatic Number of Speeds: _____

Truck Moves FWD/REV: Both

Comments: _____

Chassis:

Frame Rails: _____ Notes: _____

Suspension: Spring Notes: _____

Wheel Base: _____ in.

Axle Weight Ratings (LBS): GVWR: 52,000 Front Axle: 12,000 Rear(s): 40,000

Tire Size: Front: 275/80R22.5 Rear(s): 275/80R22.5

Comments: _____

Specialized Equipment:

Type: _____ Details: _____

Type: _____ Details: _____

Notes: _____

Notes: _____