

Trailer Condition Report:

Equipment Information:

Unit No: TM2612

Year: 2008

Make: Transcraft

Model: TL2000N

VIN/SN: 1TTF4520081083612

Miles/Hrs.: _____

Equipment Condition:

Mechanical Condition: Fair - Functioning, but in need of repair

Interior Condition: Fair - Functioning, but in need of repair

Exterior Condition: Fair - Functioning, but in need of repair

Chassis:

GVWR: _____

Suspension: Air

Tire Size: _____

Sliding Tandem Axle: _____

Braking: _____

Comments: No VIN plate

Deck

Hitch Type: _____

Dimensions: _____ Length: 45' Width: 94"

Ramps (if equipped) _____

Specialized Equipment:

Type: _____ Details: _____

Type: _____ Details: _____

Notes: _____

Notes: _____